

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
VASQUEZ	RUPERTO	43338483	TX										
MORENOVASQUEZ	RUPERTO	43338483	TX										
MORENO	RUPERTO	43338483	TX										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 5/7/2024 3:05:30 PM

MCMIS snapshot date: 04/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/08/2023	3646739	SANSUR SPECIALIZED TRANSPORT LLC	MORENO VASQUEZ, RUPERTO	43338483	TX	03/27/1982	TX	V231069598	N	2	1
Driver Violation:		392.2	Excessive Weight violation		NON-OOS							
2	08/31/2023	3646739	SANSUR SPECIALIZED TRANSPORT LLC	MORENO VASQUEZ, RUPERTO	43338483	TX	03/27/1982	TX	V231137913	N	2	5
Vehicle Violation:		393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997			NON-OOS						
Vehicle Violation:		393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998			NON-OOS						
Vehicle Violation:		393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS						
Driver Violation:		392.2	Excessive Weight violation			NON-OOS						
Driver Violation:		392.2	Excessive Weight violation			NON-OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		Excessive Weight violation							3		0	
393.11		Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997							1		0	
393.55(e)		No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998							1		0	
393.95(a)		No/discharged/unsecured fire extinguisher							1		0	

The summary counts and rates only include violations that were attributable to VASQUEZ, RUPERTO.

Report executed at: 5/7/2024 3:05:30 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.