

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
LUGO		CELIO		23099565			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		3		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			

Report executed at: 2/6/2025 11:22:56 AM

MCMIS snapshot date: 12/27/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	01/13/2022	3571051	YRP SMART TRUCKING SOLUTIONS LLC	LUGO, CELIO	23099565	TX	11/15/1967	UT	22BS000169	N	1	4
Vehicle Violation: 393.9(a) Inoperable head lamps NON-OOS Vehicle Violation: 393.205(c) Wheel fasteners loose and/or missing NON-OOS Vehicle Violation: 393.45 Brake tubing and hose adequacy NON-OOS Vehicle Violation: 396.3(a)(1) Brake system pressure loss NON-OOS												
2	04/19/2022	3571051	YRP SMART TRUCKING SOLUTIONS LLC	LUGO, CELIO	23099565	TX	11/16/1967	MS	2006011023	N	2	0
3	01/15/2023	3571051	YRP SMART TRUCKING SOLUTIONS LLC	LUGO, CELIO	23099565	TX	11/15/1967	IL	4109560307	N	3	0
4	07/03/2024	3571051	YRP SMART TRUCKING SOLUTIONS LLC	LUGO, CELIO	23099565	TX	11/15/1967	FL	2214007232	N	2	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.9(a)	Inoperable head lamps								1	0		
393.205(c)	Wheel fasteners loose and/or missing								1	0		
393.45	Brake tubing and hose adequacy								1	0		
396.3(a)(1)	Brake system pressure loss								1	0		

The summary counts and rates only include violations that were attributable to LUGO, CELIO.

Report executed at: 2/6/2025 11:22:56 AM

MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>