

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
GONZALEZ	ANDRES	A223000780210	FL										
ACOSTAGONZALEZ	ANDRES	A223000780210	FL										
ACOSTA	ANDRES	A223000780210	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%	

Report executed at: 7/10/2023 4:05:35 PM

MCMIS snapshot date: 06/30/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	09/15/2021	2594927	CUVE HOTSHOT LLC	GONZALEZ, ANDRES	A223000780210	FL	01/21/1978	NC	0006343249	N	3	0
2	11/24/2021	2594927	CUVE HOTSHOT LLC	ACOSTA, ANDRES	A223000780210	FL	01/21/1978	SD	004D011514	N	3	0
3	09/04/2022	3715907	BLACK RHINO ENERGY SERVICES INC	ACOSTA, ANDRES	A223000780210	FL	01/21/1978	TX	6E2F0MOIM2	N	2	4
<div>Vehicle Violation: 393.11 Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperable Required LampNON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperative turn signalOOS</div> <div>Vehicle Violation: 393.9(a) Inoperable Required LampNON-OOS</div>												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.11		Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997							1		0	
393.9(a)		Inoperable Required Lamp							3		1	

The summary counts and rates only include violations that were attributable to GONZALEZ, ANDRES.

Report executed at: 7/10/2023 4:05:35 PM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>