PSP Detailed Report

Federal Motor Carrier Safety Administration

		Drive	er Info	orm	ation											
Last Name	First Name		Licen	License #						State						
VALDESVALDESPINO	JOSE	JSE			45995703						ТХ					
VALDESPINO	JOSE A			45995703					ТХ							
VALDES	JOSE A		45995	45995703					ТХ							
Crash Activity																
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																
# of Crashes:	0 # of Crashes with Fatalit			0			# of Crash	nes with Ir	njuries:	0) # of To			0		
# Not preventable:	0	# of Fatal	lities:	0				# of Ir	njuries:	0) # of Hazmat R			0		
Crash Details (Crashes listed represent a d	iver's involvement	in FMCSA-reportable cra	ashes,	witl	hout any	determ	ination as to	o respon	sibility	.)						
Date DOT # Carrier Name		Driver Name	Driver Lic		State	Driver DOB	Rpt St Report Number		Number	Location	# Fatalities	# of Injuries				
Inspection Activity (3 year history from MCMIS snapshot date)																
Inspection Summary																
Driver Summary	Vehicle Summary						Hazmat Summary									
Driver Inspections:	Vehicle Inspections:					2 H	2 Hazmat Inspections									
Driver Out-of-service Inspections:	Vehicle Out-of-service Inspections:					1 H	1 Hazmat Out-of-service Inspections:									
Driver Out-of-service Rate:	50%	Vehicle Out-of-service Rate:					50% H	Hazmat Out-of-service Rate: 0%						0%		

Report executed at: 8/31/2023 1:17:55 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspec	ction Details												
Carrier Info		Driver Info	Driver Info					Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic Sta		Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	11/20/2020	2936824	JAVIER ALVARADO	VALDES VALDESPINO, JOSE	45995703	ТХ	12/31/1973	ТХ	5VXG0XIVBY	N	2	0	
2	12/28/2022	2571182	GREEN LINE FREIGHT II	VALDES VALDESPINO, JOSE	45995703	тх	12/31/1973	ТХ	6H990VMGG8	N	2	4	
	Driver Vi	Driver Violation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS									4		
		k-Tractor lower rear mud flaps retroreflective sheeting / reflex ctive material requirements for vehicles manufactured after July NON-OOS											
Vehicle Violation: 393.45(b)(2) Brak Unit		e Hose or Tubing Chafing and/or Kinking - Connection to Power OOS											
Vehicle Violation: 393.45(b)(2) Brake Unit		ke Hose or Tubing Chafing and/or Kinking - Connection to Power NON-OOS											
Violati	ion Summary												
Violation #		Description					# of Violati	ions	# of Out-of-service Violations				
395.8(a	(1) ELD - No record of duty status (ELD Required)								1		1		
393.11	393.11 Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997								1		0		
393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit								2		1			

The summary counts and rates only include violations that were attributable to VALDESVALDESPINO, JOSE.

Report executed at: 8/31/2023 1:17:55 PM MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.