



HYUNDAI
Translead

FMCSA ANNUAL INSPECTION FORM

HYUNDAI TRANSLEAD

Plant: Blvd. Hyundai No. 41, Col. Ampliación Constitución,
Playas de Rosarito, Baja California, MX. CP 22707
Corporate Office: 8880 Rio San Diego Drive, Ste # 600
San Diego, CA 92108

Inspection Facility: HT Rosarito Plant	Unit Number: <u>PTLZ244735</u>	Hubodometer (if applicable): <u>OK</u>
City and State: Rosarito, Baja California, MX.	Customer: <u>PREMIER LEASING</u>	S.A.P. Number: <u>36020917</u>
Inspector Name: <u>ALAN ESTRADA</u>	VIN Number: <u>3H3Y532K3RS19290</u>	License Plate Number: <u>45039BT</u>
Inspection Date: <u>09/05/23</u> <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Repair Date: <u>N/A</u>	Year / Model: <u>2024 / VC2530152-AJS</u>

OK	NEEDS REPAIR	ITEMS INSPECTED	OK	NEEDS REPAIR	ITEMS INSPECTED
		BRAKE SYSTEM			SAFE LOADING
/		Service Brakes	N/A		Part(s) of vehicle or condition of loading such as spare tire or any part of the load or dunnage can fall onto the roadway
/		Parking Brake System			
/		Brake Drums or Rotors			Protection against shifting cargo
/		Brake Hose			
/		Brake Tubing	N/A		STEERING MECHANISM
/		Audible Air Leaks			For units with Steerable Rear Axle.
		COUPLING DEVICES			SUSPENSION
N/A		Fifth Wheels / Upper Coupler			Any U Bolt(s), spring hanger(s) or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from it's normal position
		Pintle Hooks			
		Drawbar / Towbar Eye			Spring assembly
		Drawbar / Towbar Tongue			Torque, radius or tracking component
		Safety Devices			
		Saddle-Mounts	/		
		EXHAUST SYSTEM / REFRIGERATED UNITS			FRAME
N/A		No part of the exhaust system of any motor vehicle shall be located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle			Frame members
					Tire and Wheel Clearance
					Adjustable Axle Assemblies (Sliding Sub-Frames).
					TIRES
		FUEL SYSTEM / REFRIGERATED UNITS	N/A		WHEELS AND RIMS
N/A		Visible leak			Lock or Side Ring
		Fuel tank filler cap missing			Wheels and Rims
		Fuel tank securely attached			Fasteners
		LIGHTING DEVICES	/		Welds
/		All lighting devices and reflectors required by Section 393 shall be operable.			UNIT NUMBERS DISPLAYED
					SPLASH GUARDS
			/		Driver Side
			/		Passenger Side

I have inspected the vehicle described above and certify that all entries are true and correct. I certify that this inspection meets the requirements of 49 CFR Part 396.17 and is in accordance with Appendix G to Subchapter B, Minimum Periodic Inspection Standards, and the vehicle has passed / failed as indicated above.

INSPECTOR'S NAME (Please Print). ALAN ESTRADA

INSPECTOR'S SIGNATURE: ALAN ESTRADA