Premie	The second s	FHW	/A - P	M	Branch Inf	ormation
Trailer Number: PTLC License Number: 32 HUB Reading: 15	223218; 1449T 620	2 Location	n Inspection Perfo			ler Leasing, Inc. 201902 ook, TL.
Items Inspected and Checked	ОК	Defective	Repairs Perfe		rformed	
Lights						
Reflectors						
Wiring						
Brakes - Front						
Brakes - Rear				· · · · · · · · · · · · · · · · · · ·		
Brakes - All Adjusted						
Brake Shoe Measurements	Right Front	6 /8ths	Left Front	/8ths		
State of the second sec	Right Rear	G /8ths	Left Rear	6 /8ths	·	
Airlines						
Kingpin						
Rear Impact Guard						
Wheels & Rims						
Frame Assembly			-			
Suspension			·			
Axles						
Wheel Seals						
Check Oil Levels in Hubs						
Lubrication: Slack Adjusters						
Lubrication: Cam Bushings						
Lubrication: Landing Legs						

Tires - Air All to 100 PSI

	Tread Depth Readings	Current Air Pressure		Tread Depth Readings	Current Air Pressure
LFO	13 /32nds	200	RFO	13 /32nds	100
LFI	13 /32nds	>	RFI	13 /32nds	2
LRO	13 /32nds		RRO	13 /32nds	
LRI	13 /32nds	L	RRI	13 /32nds	(

I certify that this trailer was inspected on this 24 day of 0ch. , 20 , 20 , and made all FHWA-PI 49 C.F.R. Part #396.17through .23 requirements.

Name of Company Performing Inspection/Repairs Fix 4Less

Marc LIMINEZ

Inspectors Name (Please Print & Sign)