

FMCSA ANNUAL INSPECTION FORM HYUNDAI TRANSLEAD

Plant: Blvd. Hyundai No. 41, Col. Ampliación Constitución, Playas de Rosarito, Baja California, MX. CP 22707 Corporate Office: 8880 Rio San Diego Drive, Ste # 600 San Diego, CA 92108

Inspection Facility: HT Rosarito Plant	Unit Number: PT 12.244 738	Hubodometer (if applicable):
City and State: Rosarito, Baja California, MX.	Customer: PREMIER LEASING	S.A.P. Number: 30020917
Inspector Name: ALAN ESTRADA	VIN Number:34315 32 K9RS 119293	License Plate Number: 450401T
Inspection Date:04/05/73 Pass Fail	Repair Date: 1/14 Make: Hyundai	Year / Model: 2024 /VC2S3C152-AK

ОК	NEEDS REPAIR	ITEMS INSPECTED	ОК	NEEDS REPAIR	ITEMS INSPECTED	
		BRAKE SYSTEM		+	SAFE LOADING	
$ \neg $		Service Brakes		\square	Part(s) of vehicle or condition of loading such as	
		Parking Brake System	N	n	spare tire or any part of the load or dunnage can	
		Brake Drums or Rotors	/		fall onto the roadway	
\square		Brake Hose	1		Protection against shifting cargo	
		Brake Tubing			STEERING MECHANISM	
\square		Audible Air Leaks	N	VA	For units with Steerable Rear Axle.	
		COUPLING DEVICES			SUSPENSION	
\square		Fifth Wheels / Upper Coupler			Any U Bolt(s), spring hanger(s) or other axle	
		Pintle Hooks			positioning part(s) cracked, broken, loose or	
	[]	Drawbar / Towbar Eye			missing resulting in shifting of an axle from it's	
$ \begin{bmatrix} r \\ r \end{bmatrix} $	/F	Drawbar / Towbar Tongue			normal position	
		Safety Devices			Spring assembly	
		Saddle-Mounts		ļ	Torque, radius or tracking component	
		EXHAUST SYSTEM / REFRIGERATED UNITS			FRAME	
		No part of the exhaust system of any motor	\sim		Frame members	
1		vehicle shall be located as would be likely	<u> </u>		Tire and Wheel Clearance	
11/	At	to result in burning, charring or damaging			Adjustable Axle Assemblies (Sliding Sub-Frames).	
		the electrical wiring, the fuel supply, or any	/		TIRES	
		combustible part of the motor vehicle			WHEELS AND RIMS	
		FUEL SYSTEM / REFRIGERATED UNITS	N	YA.	Lock or Side Ring	
		Visible leak			Wheels and Rims	
	/A	Fuel tank filler cap missing			Fasteners	
		Fuel tank securely attached	/		Welds	
		LIGHTING DEVICES			UNIT NUMBERS DISPLAYED	
		All lighting devices and reflectors required			SPLASH GUARDS	
		by Section 393 shall be operable.	1		Driver Side	
					Passenger Side	

I have inspected the vehicle described above and certify that all entries are true and correct. I certify that this inspection meets the requirements of 49 CFR Part 396.17 and is in accordance with Appendix G to Subchapter B, Minimum Periodic Inspection Standards, and the vehicle has passed / failed as indicated above.

INSPECTOR'S NAME (Please Pr	rint). 🔜 🖊	4LAN	ESTAHOA	
			į	
INSPECTOR'S SIGNATURE:		ALAN	ESTRAGA	
QCD-F-600 EN	JULY/20/2012		/	

REV-03