

# DRIVER/VEHICLE EXAMINATION REPORT

Inspect 1.134.9025

Nevada State Police/Highway Patrol  
Email: Nevada.CVE@dps.state.nv.us  
Attn: Federal Projects  
555 Wright Way, Carson City, NV 89711  
Phone: 775-684-0908 Fax: 775-687-8343

Report Number: NVR117812051  
Inspection Date: 11/20/2024  
Start: 9:45 AM PT End: 10:10 AM PT  
Inspection Level: I - Full  
HM Inspection Type: None

Carrier: RIKI TRANSPORTATION INC  
DBA: BRZ

8225 LECLAIRE AVE  
BURBANK, IL, 60459

USDOT: 3119062

MC/MX#: 86875

State#:

Location: STEAD BL/SILVER LAKE PW

Highway:

County: WASHOE

Phone#: (708)303-5150

Fax#:

Driver: GONZALEZ RODRIGUEZ,  
WILFREDO

License#: G524880860120

Date of Birth: 01/12/1986

CoDriver:

License#:

Date of Birth:

State: FL

State:

Milepost:

Shipper: WB WAREHOUSING

Origin: CROCKETT, CA

Destination: SPOKANE, WA

Bill of Lading: 00540455

Cargo: COMMODITIES, DRY  
BULK

Email: RIKITRANSPORT@GMAIL.COM

## VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA #	Issued #	OOS Sticker
1	TT	FRHT	2023	IL	P1194368	607	3AKJHHDR6PSUA1610	80000		3470141	
2	ST	WANC	2023	IL	910822	7	1JJV532D4PL387175	50000			

## BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	N/A	N/A	N/A	1 3/4	2
Left	N/A	N/A	N/A	1 3/4	2 1/2
Chamber	DISC	DISC	DISC	C-30	C-30

## VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
393.47E	F	2	N		N	N	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt: axle 5 left side out of adjustment 2 1/2"
393.53B	F	2	N		N	N	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear: auto adjuster not functioning

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks:

Alcohol/Controlled Substance Check  
X Conducted by Local Jurisdiction  
Size and Weight Enforcement  
eScreen Inspection

Traffic Enforcement  
PASA Conducted Inspection  
Drug Interdiction Search

Post Crash Inspection  
PBBT Inspection

## State Information:

Destination Inspection Y or N: N; Dyed Fuel Check Y or N: N

**Advisory:** This vehicle has been identified as having brake adjustment violations. 49 CFR Section 393.53 requires that a brake system be equipped on this vehicle. A qualified service technician needs to determine why the defective brake has excessive stroke and make the appropriate repairs. Simply re-adjusting a self-adjusting brake adjuster, or replacing it, does not guarantee that the problem is corrected. The problem may exist in the foundation brake system. By certifying this inspection report you have indicated that this vehicle now has a properly functioning self-adjusting brake adjustment system.

The items listed above do not comply with Nevada law and/or regulation. It is necessary that the driver or owner return this form to the Nevada Highway Patrol within 15 days, with certification that the item(s) have been corrected. Failure to repair or correct these violations; failure to certify correction of Out-Of-Service Violations or other safety violations as noted on the Inspection Form and failure to retain a copy of the inspection form at the responsible motor carrier's principle place of business for the prescribed time period, may result in additional penalties as prescribed by law.

Signature Of Motor Carrier X: \_\_\_\_\_ Title: \_\_\_\_\_ Date: \_\_\_\_\_

