FORGU FREIGHTLINER 3440 36TH STREET S FARGO, ND 58104 701-293-9133

Ref #: 0006





SERVICE INVOICE: R101030858:01

Tag Number: 2115

# Phone Order

XXXXXXXXXXXX7760

VISA

Entry Method: Manual

Total:

\$ 607.48

DELIVER TO

**ROYAL3 INC - 18983** 6850 W 63RD STREET BEDFORD PARK IL 60638

P: (630) 405-7879

F:

08/06/24

09:18:08

Inv #: 000006 Appr Code: 04246G

Transaction ID: 304219514880340 Batch#: 000586

Customer Copy

THANK YOU!

Appryd: Online

AVS Code: ZIP MATCH Z

CVV2 Code: MATCH M

				TERMS	PURCHASE	ORDER
NVOICE	SALES TYPE	AL	OVISOR	CASH		
33:59AN	1 SRET		138		0-10-14	ODOMETER
	VIN	CUSTOMER UNIT#	ENGINE HOURS		Component Serial #	
-	3 AK IHHEG9NSNM3995	730	0	5/6/2022	80387496	305615

### **Sold Operations**

RESURFACE. NOT COVERED BY WARANTY.

**FLYWHEEL** 

HEEL OUT TO MACHINE SHOP FOR RESURFACING.

	DESCRIPTION		UNIT PRICE	EXTD PRICE
	FLYWHEEL RESURFACE	5 7 10	140.00	140.00
1 2 1		 00.00	G 11-4 6140 00	\$140.00

Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 \$140.00

Misc: \$0.00 Sublet: \$140.00

## JOB #7 01-02

COMPLAINT

REAR MAIN OIL SEAL LEAKING

CAUSE

REAR MAIN CRANK SHAFT SEAL LEAKING

CORRECTION

AFTER FLYWHEEL REMOVAL, FOUND REAR ENGINE SEAL LEAKING. GOT AUTHORIZATION TO REPLACE. REMOVED OLD SEAL, CLEANED AND INSPECTED HOUSING, BORE, AND CRANKSHAFT. ALL WERE IN USEABLE CONDITION. INSTALLED NEW SEAL PER INSTRUCTION MANUAL. CHECKED FOR OIL LEAKS AT

FLYWHEEL HOUSING AFTER ROAD TEST, NONE FOUND.

ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
LABOR 01-02-01	CUMMINS ENGINE REPAIR		273.00
		134.87	134.87
101011111111111111111111111111111111111		2.23	17.84
		0.27	3.24
		4.39	4.39
1012/110 1320		Misc: \$0.00 Sublet: \$0.00	\$433.34
	LABOR 01-02-01 101C/4965569 101D/23-12891-175 101D/PHM 8 44147 101D/PIC 4520	LABOR 01-02-01 CUMMINS ENGINE REPAIR  101C/4965569 KIT,SEAL  101D/23-12891-175 SCREW-SOCKETHEAD 12PT,1/2-20,1  101D/PHM 8 44147 TIE STRAP-15IN BLACK,NYLON, *D  101D/PIC 4520 BRAKE CLEAN	LABOR 01-02-01   CUMMINS ENGINE REPAIR   134.87   101C/4965569   KIT,SEAL   134.87   101D/23-12891-175   SCREW-SOCKETHEAD 12PT,1/2-20,1   2.23   101D/PHM 8 44147   TIE STRAP-15IN BLACK,NYLON,*D   0.27   101D/PIC 4520   BRAKE CLEAN   4.39

Parts: \$160.34

**IMPORTANT:** 

**Sold Operations Totals** 

IF SERVICE WORK HAS BEEN PERFORMED ON WHEELS, NUTS OR AXLE U-BOLTS, THEY MUST BE RETORQUED TO SPEC 25 TO 100 MILES AFTER THE SERVICE WORK HAS BEEN COMPLETED.

Labor: \$273.00

A COMPLETE QUALITY INSPECTION HAS BEEN PERFORMED ON YOUR VEHICLE

**Total Amount Due: \$607.4** 

\$573.34





		Sold Operations (Cont.)	TD PRICE
		DESCRIPTION	
QTY	ITEM	DB1 BIVOT	
1	101D/FUL 10001949	PIN, PIVOT	
	101D/FUL K4553	RELEASE YOKE ASSEMBLY KIT	
	LABOR 11-00-00	REPAIR	
		ROAD TEST	
	LABOR RT	ROAD TEST	

# JOB #2 1000-00

COMPLAINT

QUALITY INSPECTION

CAUSE

CORRECTION

1				UNIT PRICE	EXTD PRICE
11	QTY	ITEM	DESCRIPTION		
	-	LABOR 1000-00-00	QUALITY INSPECTION COMPLETED		

### JOB #5 25-00

COMPLAINT

FLYWHEEL RESURFACE. NOT COVERED BY WARANTY.

CAUSE

RESURFACE FLYWHEEL

CORRECTION

SENT FLYWHEEL OUT TO MACHINE SHOP FOR RESURFACING.

			THE PRIOR	EXTD PRICE
		DESCRIPTION	UNIT PRICE	EXIDITIOE
QTY	ITEM		140.00	140.00
1	1378L	FLYWHEEL RESURFACE	140.00	1,0,0
1	1376L		c: \$0.00 Sublet: \$1	40.00 \$140.00

Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$140.00

### JOB #7 01-02

COMPLAINT

REAR MAIN OIL SEAL LEAKING

**CAUSE** 

REAR MAIN CRANK SHAFT SEAL LEAKING

CORRECTION

AFTER FLYWHEEL REMOVAL, FOUND REAR ENGINE SEAL LEAKING. GOT AUTHORIZATION TO REPLACE. REMOVED OLD SEAL, CLEANED AND INSPECTED HOUSING, BORE, AND CRANKSHAFT. ALL WERE IN USEABLE CONDITION. INSTALLED NEW SEAL PER INSTRUCTION MANUAL. CHECKED FOR OIL LEAKS AT

FLYWHEEL HOUSING AFTER ROAD TEST, NONE FOUND.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 01-02-01	CUMMINS ENGINE REPAIR		273.00
1	101C/4965569	KIT.SEAL	134.87	134.87
8	101D/23-12891-175	SCREW-SOCKETHEAD 12PT,1/2-20,1	2.23	17.84
12	101D/PHM 8 44147	TIE STRAP-15IN BLACK,NYLON, *D	0.27	3.24
1	101D/PIC 4520	BRAKE CLEAN	4.39	4.39
		Dorto: \$160.24   Labor: \$273.00   A	Aise: \$0.00 Sublet: \$0.00	\$433.34

\$433.34 Parts: \$160.34 Labor: \$273.00 Misc: \$0.00 Sublet: \$0.00

### JOB #8 25-02

COMPLAINT

CLUTCH-REPLACEMENT KIT BROKEN IN THE BOX.

**CAUSE** 

CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	101D/ETN K4494CL	CLUTCH KIT *D		
	LABOR 25-02-00	CLUTCH-REPLACEMENT		

**Total Amount Due: \$607.48** 

\$573.34



Sold Operations Totals Parts: \$160.34 Labor: \$273.00 Misc: \$0.00 Sublet: \$140.00

IMPORTANT: IF SERVICE WORK HAS BEEN PERFORMED ON WHEELS, NUTS OR AXLE U-BOLTS, THEY MUST BE RETORQUED TO SPEC 25 TO 100 MILES AFTER THE SERVICE WORK HAS BEEN COMPLETED.

A COMPLETE QUALITY INSPECTION HAS BEEN PERFORMED ON YOUR VEHICLE

BILLED ESTIMATED No returns on electrical parts. No refunds without this invoice. 15% handling charge on all returns. \$273.00 LABOR The only warranties applying to this part(s) are those which may be offered by the manufacturer. The \$160.34 PARTS selling dealer hereby expressly disclaims all warranties, either express or implied, including any implied \$0.00 MISC warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes \$140.00 SUBLET any other person to assume for it any liability in connection with the sale of this part(s) and/or service. \$0.00 **PREPAY** Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to \$573.34 SUBTOTAL property, damages for loss of use, loss of time, loss of profit, or income, or any other incidental \$22.11 SHOP SUPPLIES damages. \$0.00 MISC SUPPLIES PAYMENT DUE BY 10TH OF MONTH FOLLOWING TERMS: NET. NO CASH DISCOUNT. \$12.03 PURCHASES. A FINANCE CHARGE OF 1.50% PER MONTH, ANNUAL RATE OF 18% WILL BE TAX CHARGED ON ALL ACCOUNTS WHICH HAVE BALANCES 30 DAYS OR MORE PAST DUE. \$607.48 TOTAL 15% HANDLING CHARGE ON ALL PARTS RETURNED FOR CREDIT OR EXCHANGE. Tell us how we did: CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL. NO RETURNS Please Remit Payment to: FARGO FREIGHTLINER AFTER 30 DAYS. PO BOX 11057 FARGO, ND 58106 Customer Signature