PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information

Last Name	First Name	License #	State
SIERRA	VICTOR	S600873620900	FL

Crash Activity

Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)

# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0

Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)

	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries

Inspection Activity (3 year history from MCMIS snapshot date)

Inspection Summary

Driver Summary		Vehicle Summary		Hazmat Summary	
Driver Inspections:	6	Vehicle Inspections:	4	Hazmat Inspections	0
Driver Out-of-service Inspections:	0	Vehicle Out-of-service Inspections:	0	Hazmat Out-of-service Inspections:	0
Driver Out-of-service Rate:	0%	Vehicle Out-of-service Rate:	0%	Hazmat Out-of-service Rate:	0%

Inspection Details

Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/03/2021	2828543	ZIGI FREIGHT INC	SIERRA, VICTOR	S600873620900	FL	03/10/1962	AL	NSXA005142	N	2	0
2	11/30/2021	2828543	ZIGI FREIGHT INC	SIERRA, VICTOR	S600873620900	FL	03/10/1962	NM	7927L9ACBG	N	2	0

Report executed at: 9/19/2023 11:58:18 AM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ

3	03/28/2022	2828543	ROYAL3 INC	SIERRA, VICTOR	S600873620900	FL	03/10/1962	MO	00SP004774	N	2	1
	Driver Violation:		395.22(g)	Portable ELD not mounted in a fixed position and visible to driver		NON-OOS						
4	04/17/2022	2828543	ROYAL3 INC	SIERRA, VICTOR	S600873620900	FL	03/10/1962	KY	CV41754483	N	1	0
5	02/17/2023	2341009	VELOX TRANSPORT SOLUTIONS LLC	SIERRA, VICTOR	S600873620900	FL	03/10/1962	VT	2161007132	N	3	2
	Driver Violation:		392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit.		NON-OOS						
	Driver Violation:		395.34(a)(1)	Failing to note malfunction that requires use of paper log		NON-OOS						
6	03/20/2023	2341009	VELOX TRANSPORT SOLUTIONS LLC	SIERRA, VICTOR	S600873620900	FL	03/10/1962	MN	0AER000491	N	3	1
	Driver Violation:		395.26(b)	Motor carrier failed to ensure that the ELD automatically recorded the required data elements.		NON-OOS						

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0
395.26(b)	Motor carrier failed to ensure that the ELD automatically recorded the required data elements.	1	0
392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit.	1	0
395.34(a)(1)	Failing to note malfunction that requires use of paper log	1	0

The summary counts and rates only include violations that were attributable to SIERRA, VICTOR.

Report executed at: 9/19/2023 11:58:18 AM

MCMIS snapshot date: 08/25/2023

For an explanation of FMCSA-reportable crashes see: https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ