

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																	
Last Name		First Name		License #		State											
OWENS		CHASE		23136306		TX											
Crash Activity																	
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0			
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0			
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries					
Inspection Activity (3 year history from MCMIS snapshot date)																	
Inspection Summary																	
Driver Summary				Vehicle Summary				Hazmat Summary									
Driver Inspections:				11		Vehicle Inspections:				10		Hazmat Inspections				4	
Driver Out-of-service Inspections:				0		Vehicle Out-of-service Inspections:				4		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:				0%		Vehicle Out-of-service Rate:				40%		Hazmat Out-of-service Rate:				0%	
Inspection Details																	
Carrier Info				Driver Info						Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol					
1	11/09/2020	1961591	VL TRUCKING INC	OWENS, CHASE (co-driver)	23136306	TX	08/21/1989	CO	PF24245391	N	1	2					
Driver Violation:				392.2		Miscellaneous Traffic Law Violation				NON-OOS - This violation does NOT apply to OWENS, CHASE.							
Vehicle Violation:				393.45(b)(2)		Brake Hose or Tubing Chafing and/or Kinking Under Vehicle				NON-OOS - This violation does NOT apply to OWENS, CHASE.							

Report executed at: 11/28/2023 12:11:35 PM

MCMIS snapshot date: 10/27/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	12/05/2020	1961591	VL TRUCKING INC	OWENS, CHASE (co-driver)	23136306	TX	08/21/1989	MS	U029003705	N	2	0
3	01/10/2021	1961591	VL TRUCKING INC	OWENS, CHASE	23136306	TX	08/21/1989	MS	U051000736	Y	1	1
Vehicle Violation:			396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination		OOS						
4	03/03/2021	1961591	VL TRUCKING INC	OWENS, CHASE	23136306	TX	08/21/1989	TN	TNTB003641	Y	2	1
Vehicle Violation:			393.75(a)(3)	Tire-flat and/or audible air leak		OOS						
5	03/16/2021	1961591	VL TRUCKING INC	OWENS, CHASE	23136306	TX	08/21/1989	VA	6226001249	Y	2	3
Driver Violation:			392.2	Excessive Weight violation		NON-OOS						
Vehicle Violation:			107.620(b)	No copy of US DOT Hazardous Materials Registration Number		NON-OOS						
Vehicle Violation:			393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997		NON-OOS						
6	05/17/2021	3488528	TRUST LINE INC	OWENS, CHASE	23136306	TX	08/21/1989	TX	60VD0VNAKP	N	2	0
7	07/12/2021	3488528	TRUST LINE INC	OWEN, CHASE	23136306	TX	08/21/1989	CA	NBEW001270	N	2	2
Vehicle Violation:			393.75(a)(2)	Tire-tread and/or sidewall separation		OOS						
Vehicle Violation:			393.75(a)(3)	Tire-flat and/or audible air leak		OOS						
8	01/18/2022	3488528	TRUST LINE INC	OWENS, CHASE	23136306	TX	08/21/1989	WA	W417003160	Y	2	3
Vehicle Violation:			172.602(c)(1)	Maintenance/accessibility of Emergency Response information		NON-OOS						
Vehicle Violation:			392.2	State vehicle registration or License Plate violation		NON-OOS						
Vehicle Violation:			392.2	State vehicle registration or License Plate violation		NON-OOS						
9	05/30/2022	3488528	TRUST LINE INC	OWENS, CHASE	23136306	TX	08/21/1989	TN	TCJT000300	N	3	0
10	07/19/2022	3488528	TRUST LINE INC	OWENS, CHASE	23136306	TX	08/21/1989	OH	3246016069	N	2	3
Vehicle Violation:			393.75(a)(3)	Tire-flat and/or audible air leak		OOS						
Vehicle Violation:			393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001		NON-OOS						
Vehicle Violation:			393.9(a)	Inoperable Required Lamp		NON-OOS						
11	06/28/2023	3527933	NOVA TERRA SOLUTIONS LLC	OWENS, CHASE	23136306	TX	08/21/1989	US	17700000-3	N	1	0

Report executed at: 11/28/2023 12:11:35 PM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	Excessive Weight violation	3	0
107.620(b)	No copy of US DOT Hazardous Materials Registration Number	1	0
393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	1	0
393.75(a)(2)	Tire-tread and/or sidewall separation	1	1
393.75(a)(3)	Tire-flat and/or audible air leak	3	3
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	1	1
172.602(c)(1)	Maintenance/accessibility of Emergency Response information	1	0
393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001	1	0
393.9(a)	Inoperable Required Lamp	1	0

The summary counts and rates only include violations that were attributable to OWENS, CHASE.

Report executed at: 11/28/2023 12:11:35 PM

MCMIS snapshot date: 10/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>