

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
FOLEY		BYRON		060590677			GA								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 12/4/2023 12:13:13 PM

MCMIS snapshot date: 11/24/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	01/09/2023	265752	FEDEX GROUND PACKAGE SYSTEM INC	FOLEY, BYRON	060590677	GA	12/31/1983	AL	MOCV003494	N	1	5
Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS Vehicle Violation: 396.3(a)(1) Brake - Leak from air chamber NON-OOS Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
2	05/04/2023	897624	MIDWEST TRADING INC	FOLEY, BYRON	060590677	GA	12/31/1983	GA	0360011883	N	2	7
Driver Violation: 395.30(b)(1) Driver failed to certify the accuracy of the information gathered by the ELD NON-OOS Driver Violation: 395.3(a)(3)(i) Driving beyond 11 hour driving limit. (Property Carrying Vehicle) NON-OOS Driver Violation: 395.3(a)(3)(i) Driving beyond 11 hour driving limit. (Property Carrying Vehicle) NON-OOS Driver Violation: 395.3(a)(2) Driving beyond 14 hour duty period (Property carrying vehicle) NON-OOS Driver Violation: 395.3(a)(2) Driving beyond 14 hour duty period (Property carrying vehicle) NON-OOS Driver Violation: 395.3(a)(2) Driving beyond 14 hour duty period (Property carrying vehicle) NON-OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
3	07/24/2023	2569327	IFS FREIGHT INC	FOLEY, BYRON	060590677	GA	12/31/1983	GA	1318004099	N	3	1
Driver Violation: 392.82(a)(1) Using a hand-held mobile telephone while operating a CMV NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.82(a)(1)	Using a hand-held mobile telephone while operating a CMV								1	0		
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD								1	0		
395.3(a)(3)(i)	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)								2	0		
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)								3	0		
393.75(a)(3)	Tire-flat and/or audible air leak								2	2		
392.2	State vehicle registration or License Plate violation								1	0		
396.3(a)(1)	Brake - Leak from air chamber								1	0		

Report executed at: 12/4/2023 12:13:13 PM

MCMIS snapshot date: 11/24/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.47(e)	Clamp or Roto type brake out-of-adjustment	1	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0

The summary counts and rates only include violations that were attributable to FOLEY, BYRON.

Report executed at: 12/4/2023 12:13:13 PM

MCMIS snapshot date: 11/24/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.