

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
COLLINS		AKEEM		C452010914210		FL									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		1	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	01/01/2020	826380		COLLINS, AKEEM	C452010914210	FL	11/21/1991	FL	FL8977160400	WILES RD	0	0			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		9		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		11%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	02/15/2022	3165413	TARA NATIONAL INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	MD	0228004930	N	1	13			

Report executed at: 12/6/2023 3:14:06 PM

MCMIS snapshot date: 11/24/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

	Driver Violation:	395.8(k)(2)	Driver failing to retain previous 7 days records of duty status	OOS									
	Driver Violation:	392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.	NON-OOS									
	Vehicle Violation:	393.209(d)	Steering system components worn, welded, or missing	OOS									
	Vehicle Violation:	393.45(d)	Brake connections with leaks or constrictions	NON-OOS									
	Vehicle Violation:	393.45(d)	Brake connections with leaks or constrictions	NON-OOS									
	Vehicle Violation:	393.45(d)	Brake connections with leaks or constrictions	NON-OOS									
	Vehicle Violation:	393.47(e)	Clamp or Roto type brake out-of-adjustment	NON-OOS									
	Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	NON-OOS									
	Vehicle Violation:	396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	OOS									
	Vehicle Violation:	396.3(a)(1)	Brake system pressure loss	OOS									
	Vehicle Violation:	393.45(b)(2)	Brake hose or tubing chafing and/or kinking	NON-OOS									
	Vehicle Violation:	393.47(e)	Clamp or Roto type brake out-of-adjustment	NON-OOS									
	Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	NON-OOS									
2	03/05/2022	3165413	TARA NATIONAL INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	MO	CT05002081	N	3	2	
	Driver Violation:	392.2	State/Local Laws - Speeding 11-14 miles per hour over the speed limit.	NON-OOS									
	Driver Violation:	392.2	Lane Restriction violation	NON-OOS									
3	05/28/2022	3165413	TARA NATIONAL INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	AR	747C000668	N	3	0	
4	06/09/2022	3165413	TARA NATIONAL INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	IA	000TTDB1GR	N	3	1	
	Driver Violation:	392.16(a)	Failing to use seat belt while operating a CMV	NON-OOS									
5	08/22/2022	3165413	TARA NATIONAL INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	OK	K200180800	N	2	0	
6	10/04/2022	3165413	TARA NATIONAL INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	CA	UBFW000681	N	3	1	
	Driver Violation:	392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit.	NON-OOS									
7	01/30/2023	3497396	SPOT EDGE TRUCKING INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	CA	N8OL006574	N	1	0	
8	04/05/2023	3497396	SPOT EDGE TRUCKING INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	SD	A003036654	N	2	1	
	Vehicle Violation:	393.75(a)(3)	Tire-flat and/or audible air leak	OOS									
9	08/22/2023	3497396	SPOT EDGE TRUCKING INC	COLLINS, AKEEM	C452010914210	FL	11/21/1991	SC	C357001546	N	3	1	

Report executed at: 12/6/2023 3:14:06 PM

MCMIS snapshot date: 11/24/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Driver Violation:	392.2	Violation of Local Laws - Explain:	NON-OOS
Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	State/Local Laws - Speeding 11-14 miles per hour over the speed limit.	5	0
392.16(a)	Failing to use seat belt while operating a CMV	1	0
395.8(k)(2)	Driver failing to retain previous 7 days records of duty status	1	1
393.209(d)	Steering system components worn, welded, or missing	1	1
393.45(d)	Brake connections with leaks or constrictions	3	0
393.47(e)	Clamp or Roto type brake out-of-adjustment	2	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	2	0
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	2	2
393.45(b)(2)	Brake hose or tubing chafing and/or kinking	1	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1

The summary counts and rates only include violations that were attributable to COLLINS, AKEEM.

Report executed at: 12/6/2023 3:14:06 PM

MCMIS snapshot date: 11/24/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.