

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
SOBERAT		HERIBERTO		000045235879			NC								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		6		Vehicle Inspections:		5		Hazmat Inspections				0			
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		17%		Vehicle Out-of-service Rate:		20%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	07/26/2021	3347638	SQ TRUCK INC	SOBERAT, HERIBERTO	000045235879	NC	04/09/1977	CA	UD98000041	N	2	0			

Report executed at: 1/9/2024 11:15:37 AM

MCMIS snapshot date: 12/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	11/16/2022	3347638	SQ TRUCK INC	SOBERAT, HERIBERTO	000045235879	NC	04/09/1977	CT	3075001372	N	1	15
	Driver Violation:	395.8(e)(1)	False report of drivers record of duty status			OOS						
	Driver Violation:	395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD			NON-OOS						
	Driver Violation:	395.24(c)(2)(ii)	Driver failed to manually add the trailer number			NON-OOS						
	Vehicle Violation:	393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS						
	Vehicle Violation:	393.95(f)	No / insufficient warning devices			NON-OOS						
	Vehicle Violation:	393.75(a)	Flat tire or fabric exposed			OOS						
	Vehicle Violation:	396.3(a)(1)	Brake system pressure loss			OOS						
	Vehicle Violation:	393.48(a)	Inoperative/defective brakes			NON-OOS						
	Vehicle Violation:	393.48(a)	Inoperative/defective brakes			NON-OOS						
	Vehicle Violation:	393.48(a)	Inoperative/defective brakes			NON-OOS						
	Vehicle Violation:	393.48(a)	Inoperative/defective brakes			NON-OOS						
	Vehicle Violation:	396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination			OOS						
	Vehicle Violation:	396.3(a)(1)	Brake system pressure loss			NON-OOS						
	Vehicle Violation:	393.9(a)	Inoperable Required Lamp			NON-OOS						
	Vehicle Violation:	393.11	No or defective lighting devices or reflective material as required			NON-OOS						
3	02/06/2023	3347638	SQ TRUCK INC	SOBERAT, HERIBERTO	000045235879	NC	04/09/1977	CT	3015001847	N	2	5
	Driver Violation:	391.11(b)(2)	Driver cannot read or speak the English language sufficiently to respond to official inquiries.			NON-OOS						
	Driver Violation:	395.24(d)	ELD cannot transfer ELD records electronically			NON-OOS						
	Vehicle Violation:	393.81	Horn inoperative			NON-OOS						
	Vehicle Violation:	393.11	Truck-Tractor with No retroreflective sheeting or reflex reflective material on vehicle manufactured after July 1997			NON-OOS						
	Vehicle Violation:	392.2	Miscellaneous Traffic Law Violation			NON-OOS						
4	08/29/2023	1351000	JORDAN HOLDINGS INC	SOBERAT, HERIBERTO	000045235879	NC	04/09/1977	TN	TBWO000456	N	3	0
5	09/18/2023	1351000	JORDAN HOLDINGS INC	SOBERAT, HERIBERTO	000045235879	NC	04/09/1977	MT	L327000005	N	1	0
6	12/02/2023	1351000	JORDAN HOLDINGS INC	SOBERAT, HERIBERTO	000045235879	NC	04/09/1977	FL	3186006459	N	2	0

Report executed at: 1/9/2024 11:15:37 AM

MCMIS snapshot date: 12/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
395.8(e)(1)	False report of drivers record of duty status	1	1
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	1	0
395.24(c)(2)(ii)	Driver failed to manually add the trailer number	1	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.95(f)	No / insufficient warning devices	1	0
393.75(a)	Flat tire or fabric exposed	1	1
396.3(a)(1)	Brake system pressure loss	3	2
393.48(a)	Inoperative/defective brakes	4	0
393.9(a)	Inoperable Required Lamp	1	0
393.11	No or defective lighting devices or reflective material as required	2	0
391.11(b)(2)	Driver cannot read or speak the English language sufficiently to respond to official inquiries.	1	0
395.24(d)	ELD cannot transfer ELD records electronically	1	0
393.81	Horn inoperative	1	0
392.2	Miscellaneous Traffic Law Violation	1	0

The summary counts and rates only include violations that were attributable to SOBERAT, HERIBERTO.

Report executed at: 1/9/2024 11:15:37 AM

MCMIS snapshot date: 12/29/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.