

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
SACREIZQUIERDO	JOEL	S262420701761	FL										
SACRE	JOEL	S262420701761	FL										
IZQUIERDO	JOEL	S262420701761	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		5		Vehicle Inspections:		3		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		33%		Hazmat Out-of-service Rate:				0%	

Report executed at: 1/29/2024 2:21:39 PM

MCMIS snapshot date: 12/29/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	02/01/2021	2325792	TWIN BROTHERS TRANSPORT CORP	SACRE, JOEL	S262420701761	FL	05/16/1970	MS	6601000108	N	3	2
Driver Violation: 387.301(a) No evidence of public liability and property damage insurance NON-OOS Driver Violation: 395.3(a)(2) Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation NON-OOS												
2	01/25/2022	2936117	H & D TRUCKING CORP	SACRE IZQUIERDO, JOEL	S262420701761	FL	05/16/1970	VA	6118001259	N	1	9
Vehicle Violation: 393.11 Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.55(c)(1) Truck Tractor manufactured after March 1, 1997 not equipped with an antilock brake system. NON-OOS Vehicle Violation: 393.11 No or defective lighting devices or reflective material as required NON-OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS Vehicle Violation: 393.48(a) Inoperative/defective brakes NON-OOS Vehicle Violation: 396.3(a)(1) Brakes (general) Explain: OOS Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS												
3	07/19/2022	1437731	STAR TRANSPORTATION PA INC	SACRE IZQUIERDO, JOEL	S262420701761	FL	05/16/1970	MA	CJ00001230	N	3	1
Driver Violation: 392.82(a)(1) Using a hand-held mobile telephone while operating a CMV NON-OOS												
4	11/14/2022	2160371	COAST TO COAST EXPRESS CARRIER LLC	SACRE IZQUIERDO, JOEL	S262420701761	FL	05/16/1970	FL	3706004591	N	2	0
5	04/02/2023	3442559	ROAD MARK FREIGHT LLC	SACRE, JOEL	S262420701761	FL	05/16/1970	TX	6JWE0XTV4L	N	2	1
Vehicle Violation: 396.3(a)(1) Brakes (general) Explain: NON-OOS												

Report executed at: 1/29/2024 2:21:39 PM

MCMIS snapshot date: 12/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	2	0
393.55(c)(1)	Truck Tractor manufactured after March 1, 1997 not equipped with an antilock brake system.	1	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
393.47(e)	Clamp or Roto type brake out-of-adjustment	1	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
393.48(a)	Inoperative/defective brakes	1	0
396.3(a)(1)	Brakes (general) Explain:	3	2
392.82(a)(1)	Using a hand-held mobile telephone while operating a CMV	1	0
387.301(a)	No evidence of public liability and property damage insurance	1	0
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation	1	0

The summary counts and rates only include violations that were attributable to SACREIZQUIERDO, JOEL.

Report executed at: 1/29/2024 2:21:39 PM

MCMIS snapshot date: 12/29/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>