

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
RODASLOPEZ		GABRIEL		942221032			AR								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		5		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	12/17/2021	65769	HIRSCHBACH MOTOR LINES INC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	KS	HP93412067	N	3	0			

Report executed at: 2/16/2024 11:01:57 AM

MCMIS snapshot date: 01/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	09/08/2022	3218214	NIKI EXPRESS INC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	TN	TEQM006692	N	1	2
Vehicle Violation:			393.75(a)(3)	Tire-flat and/or audible air leak		OOS						
Vehicle Violation:			393.45(d)	Brake connections with leaks or constrictions		OOS						
3	04/04/2023	3757116	EAS LOGISTICS LLC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	SC	B366000623	N	2	3
Vehicle Violation:			393.95(a)	No/discharged/unsecured fire extinguisher		NON-OOS						
Vehicle Violation:			393.75(b)	Tire-front tread depth less than 4/32 of inch on a major tread groove		NON-OOS						
Vehicle Violation:			396.17(c)	Operating a CMV without proof of a periodic inspection		NON-OOS						
4	05/11/2023	3300306	HOOK N BOOK TOWING LLC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	MO	W100000673	N	1	6
Vehicle Violation:			392.2	State or International Fuel Tax (IFTA) Violation		NON-OOS						
Vehicle Violation:			393.95(a)	No/discharged/unsecured fire extinguisher		NON-OOS						
Vehicle Violation:			376.11(d)(1)	Lease or Rental Agreement not on board leased or rented CMV		NON-OOS						
Vehicle Violation:			393.25(f)	Stop lamp violations		NON-OOS						
Vehicle Violation:			393.11	Upper Rear retroreflective sheeting or reflex reflecting material requirements for vehicles manufactured after December 1993		NON-OOS						
Vehicle Violation:			393.207(b)	Adjustable axle locking pins missing or not engaged		NON-OOS						
5	11/07/2023	2289209	MEIBORG INC	RODAS LOPEZ, GABRIEL	942221032	AR	05/26/1984	MI	PEIFM05884	N	2	6
Vehicle Violation:			393.9(a)	Inoperable Required Lamp		NON-OOS						
Vehicle Violation:			393.9(a)	Inoperable Required Lamp		NON-OOS						
Vehicle Violation:			393.9(a)	Inoperative Brake Lamps		OOS						
Vehicle Violation:			393.9(a)	Inoperable tail lamp		OOS						
Vehicle Violation:			393.9(a)	Inoperable Required Lamp		NON-OOS						
Vehicle Violation:			393.9(a)	Inoperable Required Lamp		NON-OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.75(a)(3)		Tire-flat and/or audible air leak							1			
393.45(d)		Brake connections with leaks or constrictions							1			
393.95(a)		No/discharged/unsecured fire extinguisher							2			
393.75(b)		Tire-front tread depth less than 4/32 of inch on a major tread groove							1			
396.17(c)		Operating a CMV without proof of a periodic inspection							1			
392.2		State or International Fuel Tax (IFTA) Violation							1			
376.11(d)(1)		Lease or Rental Agreement not on board leased or rented CMV							1			

Report executed at: 2/16/2024 11:01:57 AM

MCMIS snapshot date: 01/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.25(f)	Stop lamp violations	1	0
393.11	Upper Rear retroreflective sheeting or reflex reflecting material requirements for vehicles manufactured after December 1993	1	0
393.207(b)	Adjustable axle locking pins missing or not engaged	1	0
393.9(a)	Inoperable Required Lamp	6	2

The summary counts and rates only include violations that were attributable to RODASLOPEZ, GABRIEL.

Report executed at: 2/16/2024 11:01:57 AM

MCMIS snapshot date: 01/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.