

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
DORSETT		GREGORY		10951038		TX									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		7		Vehicle Inspections:		6		Hazmat Inspections				0			
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		14%		Vehicle Out-of-service Rate:		17%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	04/08/2021	2959800	GLOBAL TRANS SYSTEM INC	DORSETT, GREGORY	10951038	TX	04/12/1961	TX	5ZS90XJXBZ	N	2	1			
Vehicle Violation:		393.207(f)		Air suspension pressure loss		NON-OOS									

Report executed at: 4/8/2024 11:20:16 AM

MCMIS snapshot date: 04/04/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	04/12/2021	2959800	GLOBAL TRANS SYSTEM INC	DORSETT, GREGORY	10951038	TX	04/12/1961	FL	2146002243	N	2	3
Driver Violation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS Vehicle Violation: 392.2 Dimension Violation (Width / Height / Length) NON-OOS Driver Violation: 395.8(f)(1) Drivers record of duty status not current NON-OOS												
3	06/23/2021	2575530	CRC OILFIELD SERVICES LLC	DORSETT, GREGORY	10951038	TX	04/12/1961	FL	2426001435	N	2	11
Driver Violation: 392.2 Failure to obey traffic control device NON-OOS Driver Violation: 395.22(h)(4) Driver failed to maintain supply of blank drivers records of duty status graph-grids NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 393.78 Windshield wipers inoperative/defective NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.11 Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.48(a) Brakes - Severe rusting of brake rotor (disc) NON-OOS Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal OOS												
4	10/19/2021	2959800	GLOBAL TRANS SYSTEM INC	DORSETT, GREGORY	10951038	TX	04/12/1961	NY	SPB0360312	N	2	3
Vehicle Violation: 392.2 State or International Fuel Tax (IFTA) Violation NON-OOS Vehicle Violation: 393.9(a) Inoperable tail lamp NON-OOS Vehicle Violation: 393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001 NON-OOS												
5	11/17/2021	2959800	GLOBAL TRANS SYSTEM INC	DORSETT, GREGORY	10951038	TX	04/12/1961	MS	2019010492	N	1	0
6	05/25/2022	3180712	FORWARD TRUCKING INC	DORSETT, GREGORY	10951038	TX	04/12/1961	AZ	0306113619	N	3	6

Report executed at: 4/8/2024 11:20:16 AM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

	Driver Violation:	392.16(a)	Failing to use seat belt while operating a CMV	NON-OOS								
	Driver Violation:	395.24(c)(2)(ii)	Driver failed to manually add the trailer number	NON-OOS								
	Driver Violation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number	NON-OOS								
	Driver Violation:	395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	NON-OOS								
	Driver Violation:	395.8(e)(1)	False report of drivers record of duty status	NON-OOS								
	Driver Violation:	395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	NON-OOS								
7	04/05/2023	3633871	EPIC TOOL & RENTAL INC	DORSETT, GREGORY	10951038	TX	04/12/1961	TX	V231011454	N	2	2
	Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS								
	Vehicle Violation:	396.17(c)	Operating a CMV without proof of a periodic inspection	NON-OOS								

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
395.8(a)(1)	ELD - No record of duty status (ELD Required)	1	1
392.2	Dimension Violation (Width / Height / Length)	4	0
395.8(f)(1)	Drivers record of duty status not current	1	0
395.22(h)(4)	Driver failed to maintain supply of blank drivers records of duty status graph-grids	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	3	0
393.78	Windshield wipers inoperative/defective	1	0
393.9(a)	Inoperable Required Lamp	5	1
393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997	1	0
393.48(a)	Brakes - Severe rusting of brake rotor (disc)	1	0
392.16(a)	Failing to use seat belt while operating a CMV	1	0
395.24(c)(2)(ii)	Driver failed to manually add the trailer number	1	0
395.24(c)(2)(iii)	Driver failed to manually add shipping document number	1	0
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	1	0
395.8(e)(1)	False report of drivers record of duty status	1	0
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0
393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001	1	0
393.207(f)	Air suspension pressure loss	1	0

The summary counts and rates only include violations that were attributable to DORSETT, GREGORY.

Report executed at: 4/8/2024 11:20:16 AM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>