

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
HENDRIETH	IVAN	H536689583650	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary			Vehicle Summary				Hazmat Summary						
Driver Inspections:	10		Vehicle Inspections:	4		Hazmat Inspections					0		
Driver Out-of-service Inspections:	1		Vehicle Out-of-service Inspections:	1		Hazmat Out-of-service Inspections:					0		
Driver Out-of-service Rate:	10%		Vehicle Out-of-service Rate:	25%		Hazmat Out-of-service Rate:					0%		

Report executed at: 4/10/2024 7:25:57 PM

MCMIS snapshot date: 04/04/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	11/09/2021	1836881	EB TRANSPORT INC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	KY	CV44112861	N	1	4
Driver Violation:		392.2	Violation of Local Laws - Explain:			NON-OOS						
Driver Violation:		392.2	State or International Fuel Tax (IFTA) Violation			NON-OOS						
Driver Violation:		392.2	Violation of Local Laws - Explain:			NON-OOS						
Vehicle Violation:		393.45	Brake Tubing and Hose Adequacy - Connections to Power Unit			OOS						
2	02/21/2022	1836881	EB TRANSPORT INC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	AZ	0314000931	N	3	0
3	08/26/2022	2002349	FREIGHT ONE INC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	IA	000TT7D6SN	N	3	1
Driver Violation:		392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit.			NON-OOS						
4	09/22/2022	2002349	FREIGHT ONE INC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	IL	4070210052	N	2	0
5	11/05/2022	2002349	FREIGHT ONE INC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	OH	3274024736	N	2	2
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
6	02/21/2023	3695031	GLOBAL M TRANSPORT LLC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	SC	S349001104	N	3	3
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status			NON-OOS						
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status			OOS						
Driver Violation:		395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD			NON-OOS						
7	05/01/2023	3695031	GLOBAL M TRANSPORT LLC	HENDRIETH, IVAN	H536689583650	FL	10/05/1958	OH	0992007911	N	2	3
Vehicle Violation:		393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.47(d)	All Brakes - Insufficient brake lining thickness			NON-OOS						
8	06/20/2023	3695031	GLOBAL M TRANSPORT LLC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	SC	J217007992	N	3	0

Report executed at: 4/10/2024 7:25:57 PM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

9	09/28/2023	3487141	TUTASH	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	IL	4069130304	N	3	0
10	12/14/2023	1811206	MVV LINES INC	HENDRIETH, PAUL	H536689583650	FL	10/05/1958	IL	4127400705	N	3	0

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit.	4	0
395.8(e)(1)	False report of drivers record of duty status	2	1
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	1	0
393.9(a)	Inoperable Required Lamp	3	0
393.45	Brake Tubing and Hose Adequacy - Connections to Power Unit	1	1
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
393.47(d)	All Brakes - Insufficient brake lining thickness	1	0

The summary counts and rates only include violations that were attributable to HENDRIETH, IVAN.

Report executed at: 4/10/2024 7:25:57 PM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>