

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
PERALTA	HENRY	P643380860420	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		5		Vehicle Inspections:		4		Hazmat Inspections			0		
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:			0		
Driver Out-of-service Rate:		20%		Vehicle Out-of-service Rate:		25%		Hazmat Out-of-service Rate:			0%		
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	04/27/2021	3488861	PERALTA TRANSPORT LLC	PERALTA, HENRY	P643380860420	FL	02/02/1986	CA	ND3G002414	N	1	0	
2	06/01/2021	3488861	PERALTA TRANSPORT LLC	PARALTA, HENRY	P643380860420	FL	02/02/1986	TN	TCGS006675	N	2	1	
Vehicle Violation:		396.5(b)		Hubs - Wheel seal leaking - outer wheel				OOS					

Report executed at: 5/3/2024 3:56:41 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

3	11/30/2021	3488861	PERALTA TRANSPORT LLC	PERALTA, HENRY	P643380860420	FL	02/02/1986	OH	3246015366	N	2	2
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001			NON-OOS						
4	03/20/2022	3488861	PERALTA TRANSPORT LLC	PERALTA, HENRY	P643380860420	FL	02/02/1986	AL	SBAB000978	N	3	0
5	10/01/2023	3586456	PERFORMANCE HAULING INC	PERALTA, HENRY	P643380860420	FL	02/02/1986	TX	6OYA9DCKO8	N	2	5
Vehicle Violation:		396.17(c)	Operating a CMV without proof of a periodic inspection			NON-OOS						
Vehicle Violation:		393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS						
Driver Violation:		383.23(a)(2)	Operating a CMV without a CDL			OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove			NON-OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.9(a)		Inoperable Required Lamp							2		0	
393.55(d)(3)		No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001							1		0	
396.17(c)		Operating a CMV without proof of a periodic inspection							1		0	
393.95(a)		No/discharged/unsecured fire extinguisher							1		0	
383.23(a)(2)		Operating a CMV without a CDL							1		1	
393.75(c)		Tire-other tread depth less than 2/32 of inch measured in a major tread groove							1		0	
396.5(b)		Hubs - Wheel seal leaking - outer wheel							1		1	

The summary counts and rates only include violations that were attributable to PERALTA, HENRY.

Report executed at: 5/3/2024 3:56:41 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>