

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
GLENN		DAVID		098008748		TN									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:				4		Vehicle Inspections:				3		Hazmat Inspections		0	
Driver Out-of-service Inspections:				0		Vehicle Out-of-service Inspections:				1		Hazmat Out-of-service Inspections:		0	
Driver Out-of-service Rate:				0%		Vehicle Out-of-service Rate:				33%		Hazmat Out-of-service Rate:		0%	
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	08/22/2021	2551863	RR TRANS SYSTEMS INC	GLENN, DAVID	098008748	TN	12/16/1985	MO	W133003910	N	1	3			
Vehicle Violation:		393.9(a)		Inoperative turn signal		NON-OOS									
Vehicle Violation:		393.9(a)		Inoperable tail lamp		NON-OOS									
Vehicle Violation:		393.75(c)		Tire-other tread depth less than 2/32 of inch measured in a major tread groove		NON-OOS									

Report executed at: 5/13/2024 10:58:29 AM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	01/26/2022	3462266	PRIMEX FREIGHT LLC	GLENN, DAVID	098008748	TN	12/16/1985	KS	HP04680198	N	3	1
Driver Violation:			392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit.			NON-OOS					
3	07/21/2023	2589591	EGZIT CORPORATION	GLENN, DAVID	098008748	TN	12/16/1985	KY	S197001146	N	2	0
4	01/29/2024	839281	UNIVERSAL LOGISTICS SERVICES INC	GLENN, DAVID	098008748	TN	12/16/1985	KY	CV44840182	N	1	1
Vehicle Violation:			393.75(a)	Flat tire or fabric exposed			OOS					
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		State/Local Laws - Speeding 6-10 miles per hour over the speed limit.							1		0	
393.75(a)		Flat tire or fabric exposed							1		1	
393.9(a)		Inoperative turn signal							2		0	
393.75(c)		Tire-other tread depth less than 2/32 of inch measured in a major tread groove							1		0	

The summary counts and rates only include violations that were attributable to GLENN, DAVID.

Report executed at: 5/13/2024 10:58:29 AM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>