

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
OSORIO		SILVIO		O260787763210			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		5		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	05/04/2021	3176429	MIRELA'S COMPANY INC	OSORIO, SILVIO	O260787763210	FL	09/01/1976	CO	5B01001187	N	3	1			
Driver Violation:		392.2		Failure to Maintain Lane				NON-OOS							

Report executed at: 5/28/2024 2:32:24 PM

MCMIS snapshot date: 04/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	08/24/2021	3176429	MIRELA'S COMPANY INC	OSORIO, SILVIO	O260787763210	FL	09/01/1976	NM	4205L6KBLT	N	1	2
Vehicle Violation:			393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS					
Vehicle Violation:			393.205(c)	Wheel fasteners loose and/or missing			OOS					
3	09/16/2021	3176429	MIRELA'S COMPANY INC	OSORIO, SILVIO GABRIEL	O260787763210	FL	09/01/1976	IN	9511001835	N	1	5
Driver Violation:			392.2	State/Local Laws - Excessive weight - 2501-5000 lbs over on an axle/axle groups.			NON-OOS					
Vehicle Violation:			393.45(d)	Brake Connections with Leaks Under Vehicle			NON-OOS					
Vehicle Violation:			393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS					
Driver Violation:			395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)			NON-OOS					
Driver Violation:			395.26(b)	Motor carrier failed to ensure that the ELD automatically recorded the required data elements.			NON-OOS					
4	12/13/2021	1542003	TEAM LLANOS INC	OSORIO, SILVIO	O260787763210	FL	09/01/1976	KS	HP00340088	N	2	3
Vehicle Violation:			393.11	Upper Rear retroreflective sheeting or reflex reflecting material requirements for vehicles manufactured after December 1993			NON-OOS					
Vehicle Violation:			393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997			NON-OOS					
Vehicle Violation:			393.9(a)	Inoperable Required Lamp			NON-OOS					
5	02/01/2022	3176429	MIRELA'S COMPANY INC	OSORIO, SILVIO	O260787763210	FL	09/01/1976	MD	0296003850	N	2	1
Vehicle Violation:			396.3(a)(1)	Inspection, repair and maintenance of parts and accessories			OOS					
6	08/26/2023	1437731	STAR TRANSPORTATION PA INC	OSORIO, SILVIO	O260787763210	FL	09/01/1976	CA	NEEX001874	N	4	2
Vehicle Violation:			393.45	Brake tubing and hose adequacy			OOS					
Vehicle Violation:			396.3(a)(1)	Inspection, repair and maintenance of parts and accessories			NON-OOS					
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.95(a)		No/discharged/unsecured fire extinguisher							2		0	
393.205(c)		Wheel fasteners loose and/or missing							1		1	
392.2		State/Local Laws - Excessive weight - 2501-5000 lbs over on an axle/axle groups.							2		0	
393.45(d)		Brake Connections with Leaks Under Vehicle							1		0	
395.3(a)(2)		Driving beyond 14 hour duty period (Property carrying vehicle)							1		0	
395.26(b)		Motor carrier failed to ensure that the ELD automatically recorded the required data elements.							1		0	
393.45		Brake tubing and hose adequacy							1		1	
396.3(a)(1)		Inspection, repair and maintenance of parts and accessories							2		1	
393.11		Upper Rear retroreflective sheeting or reflex reflecting material requirements for vehicles manufactured after December 1993							2		0	

Report executed at: 5/28/2024 2:32:24 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.9(a)	Inoperable Required Lamp	1	0
----------	--------------------------	---	---

The summary counts and rates only include violations that were attributable to OSORIO, SILVIO.

Report executed at: 5/28/2024 2:32:24 PM

MCMIS snapshot date: 04/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.