

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
BAYARD		BAYARD		B630160762441		FL									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		1		# of Towaways:		1	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		1		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	09/23/2021	3145664	VAMAR INC	BAYARD, DUTHENE	B630160762441	FL	07/04/1976	CO	CO2021001389	I70 .50 MILES FROM MP 244	0	1			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		5		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			

Report executed at: 6/5/2024 1:40:38 PM

MCMIS snapshot date: 04/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/16/2021	3145664	VAMAR INC	BAYARD, DUTHENE	B630160762441	FL	07/04/1976	OK	PE12003486	N	1	5
Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS Driver Violation: 395.8 Record of Duty Status violation (general/form and manner) NON-OOS Driver Violation: 395.22(h)(2) Driver failing to maintain ELD instruction sheet NON-OOS Driver Violation: 395.22(g) Portable ELD not mounted in a fixed position and visible to driver NON-OOS												
2	09/23/2021	3145664	VAMAR INC	DUTHENE, BAYARD	B630160762441	FL	07/04/1976	CO	1A47000051	N	3	0
3	08/02/2022	2330774	TRX EXPRESS INC	BAYARD, DUTHENE	B630160762441	FL	07/04/1976	IN	7018007867	N	3	1
Driver Violation: 392.2 State/Local Laws - Speeding work/construction zone. NON-OOS												
4	12/02/2022	2330774	TRX EXPRESS INC	BAYARD, DUTHENE	B630160762441	FL	07/04/1976	MO	W132006263	N	1	1
Driver Violation: 392.2 State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups. NON-OOS												
5	03/09/2024	2564300	BURTON ENTERPRISES LLC	BAYARD, DUTHENE	B630160762441	FL	07/04/1976	ID	2866008929	N	3	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt								1	0		
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear								1	0		
395.8	Record of Duty Status violation (general/form and manner)								1	0		
395.22(h)(2)	Driver failing to maintain ELD instruction sheet								1	0		
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver								1	0		
392.2	State/Local Laws - Speeding work/construction zone.								2	0		

The summary counts and rates only include violations that were attributable to BAYARD, BAYARD.

Report executed at: 6/5/2024 1:40:38 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>