

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
MELENDEZHERRERA	OSCAR	M453650863350	FL										
MELENDEZ	OSCAR	M453650863350	FL										
HERRERA	OSCAR	M453650863350	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%	
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	05/12/2023	3570443	WAVE STREAM LOGISTICS LLC	MELENDEZ HERRERA, OSCAR	M453650863350	FL	09/15/1986	NY	0325002041	N	1	19	

Report executed at: 7/2/2024 9:52:40 AM

MCMIS snapshot date: 05/31/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

	Driver Violation:	395.8(e)(1)	False report of drivers record of duty status	NON-OOS								
	Driver Violation:	395.8(e)(1)	False report of drivers record of duty status	NON-OOS								
	Driver Violation:	395.32(b)	Driver failed to assume or decline unassigned driving time	NON-OOS								
	Driver Violation:	395.24(c)(1)(ii)	Driver failed to manually add location description	NON-OOS								
	Vehicle Violation:	396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	OOS								
	Vehicle Violation:	393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	NON-OOS								
	Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	NON-OOS								
	Vehicle Violation:	393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	NON-OOS								
	Vehicle Violation:	396.3(a)(1)	Brake system pressure loss	NON-OOS								
	Vehicle Violation:	393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	NON-OOS								
	Vehicle Violation:	393.9(a)	Inoperative turn signal	OOS								
	Vehicle Violation:	393.207(a)	Axle positioning parts defective/missing	NON-OOS								
	Vehicle Violation:	393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	NON-OOS								
	Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	NON-OOS								
	Vehicle Violation:	393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	NON-OOS								
	Vehicle Violation:	393.11	No or defective lighting devices or reflective material as required	NON-OOS								
	Vehicle Violation:	393.9(a)	Inoperable Required Lamp	NON-OOS								
	Vehicle Violation:	393.9(a)	Inoperative turn signal	NON-OOS								
	Vehicle Violation:	393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	NON-OOS								
2	06/03/2023	3570443	WAVE STREAM LOGISTICS LLC	MELLENDEZ HERRERA, OSCAR	M453650863350	FL	09/15/1986	FL	3227020331	N	3	6
	Driver Violation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number	NON-OOS								
	Driver Violation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number	NON-OOS								
	Driver Violation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number	NON-OOS								
	Driver Violation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number	NON-OOS								
	Driver Violation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number	NON-OOS								
	Driver Violation:	395.24(c)(2)(iii)	Driver failed to manually add shipping document number	NON-OOS								
3	03/26/2024	2989027	AMERICAN EXPRESS FREIGHT INC	MELLENDEZ HERRERA, OSCAR	M453650863350	FL	09/15/1986	WI	2645002621	N	2	0

Report executed at: 7/2/2024 9:52:40 AM

MCMIS snapshot date: 05/31/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
395.8(e)(1)	False report of drivers record of duty status	2	0
395.32(b)	Driver failed to assume or decline unassigned driving time	1	0
395.24(c)(1)(ii)	Driver failed to manually add location description	1	0
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	2	1
393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	3	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	2	0
393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	2	0
393.9(a)	Inoperative turn signal	3	1
393.207(a)	Axle positioning parts defective/missing	1	0
393.11	No or defective lighting devices or reflective material as required	1	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
395.24(c)(2)(iii)	Driver failed to manually add shipping document number	6	0

The summary counts and rates only include violations that were attributable to MELENDEZHERRERA, OSCAR.

Report executed at: 7/2/2024 9:52:40 AM

MCMIS snapshot date: 05/31/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>