

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
ROJASECHEMENDIA		MICHAEL		R222540852060		FL									
ROJAS		MICHEL		R222540852060		FL									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:				7		Vehicle Inspections:				5		Hazmat Inspections		0	
Driver Out-of-service Inspections:				2		Vehicle Out-of-service Inspections:				0		Hazmat Out-of-service Inspections:		0	
Driver Out-of-service Rate:				29%		Vehicle Out-of-service Rate:				0%		Hazmat Out-of-service Rate:		0%	
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	12/12/2021	3565940	R&R TRANSPORTATION LLC	ROJAS, MICHEL	R222540852060	FL	06/06/1985	TX	66O90VBUQP	N	2	2			
Driver Violation:		391.45(b)		Expired medical examiner's certificate				NON-OOS							
Vehicle Violation:		393.75(c)		Tire-other tread depth less than 2/32 of inch measured in a major tread groove				NON-OOS							

Report executed at: 12/12/2024 12:18:28 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	08/04/2022	3908571	OTF TRANSPORTATION INC	ROJAS ECHEMENDIA, MICHEL	R222540852060	FL	06/06/1985	FL	1404004893	N	3	0
3	09/26/2022	3908571	OTF TRANSPORTATION INC	ROJAS ECHEMENDIA, MICHEL	R222540852060	FL	06/06/1985	AZ	0268003741	N	2	14
Driver Violation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS Driver Violation: 395.8 Record of Duty Status violation (general/form and manner) NON-OOS Driver Violation: 395.8 Record of Duty Status violation (general/form and manner) NON-OOS Driver Violation: 395.8 Record of Duty Status violation (general/form and manner) NON-OOS Vehicle Violation: 393.55(c)(1) Truck Tractor manufactured on or after March 1, 1997 not equipped with an antilock brake system NON-OOS Vehicle Violation: 393.55(d)(2) CMV manufactured on/after 3/1/2001 not equipped with ABS malfunction circuit / lamp from towed vehicle in cab NON-OOS Vehicle Violation: 392.2 State Insurance Violation NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.11 Side retroreflective sheeting or reflex reflector requirements for vehicles manufactured after December 1993 NON-OOS Vehicle Violation: 393.11 No Lower rear retroreflective sheeting or reflex reflective materials as required for vehicles manufactured after December 1993 NON-OOS Vehicle Violation: 393.11 No Lower rear retroreflective sheeting or reflex reflective materials as required for vehicles manufactured after December 1993 NON-OOS												
4	10/20/2022	3908571	OTF TRANSPORTATION INC	ROJAS ECHEMENDIA, MICHEL	R222540852060	FL	06/06/1985	AL	BIME001091	N	2	2
Driver Violation: 392.2 State/Local Laws - Speeding 6-10 miles per hour over the speed limit NON-OOS Driver Violation: 392.2 Improper lane change NON-OOS												
5	03/12/2023	4001327	MRE LOGISTICS LLC	ROJAS ECHEMENDIA, MICHAEL	R222540852060	FL	06/06/1985	AZ	OY2V001436	N	1	11

Report executed at: 12/12/2024 12:18:28 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Driver Violation:	395.8(a)(1)	ELD - No record of duty status (ELD Required)	OOS
Driver Violation:	395.8	Record of Duty Status violation (general/form and manner)	NON-OOS
Driver Violation:	395.8	Record of Duty Status violation (general/form and manner)	NON-OOS
Driver Violation:	395.8	Record of Duty Status violation (general/form and manner)	NON-OOS
Vehicle Violation:	393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle	NON-OOS
Vehicle Violation:	393.11	Upper Rear retroreflective sheeting or reflex reflecting material requirements for vehicles manufactured after December 1993	NON-OOS
Vehicle Violation:	393.45(d)	Brake connections with leaks or constrictions	NON-OOS
Vehicle Violation:	393.78	Wipers - Inoperative / missing / damaged wipers	NON-OOS
Vehicle Violation:	393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	NON-OOS
Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	NON-OOS
Vehicle Violation:	393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001	NON-OOS

6	04/23/2024	4101952	SALERMO CONNECTION INC	ROJAS ECHEMENDIA, MICHEL	R222540852060	FL	06/06/1985	GA	1264000031	N	3	0
---	------------	---------	------------------------	--------------------------	---------------	----	------------	----	------------	---	---	---

7	10/27/2024	4197900	APEX FREIGHT SERVICES LLC	ROJAS ECHEMENDIA, MICHEL	R222540852060	FL	06/06/1985	AZ	1012700981	N	2	0
---	------------	---------	---------------------------	--------------------------	---------------	----	------------	----	------------	---	---	---

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
391.45(b)	Expired medical examiner's certificate	1	0
393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	1	0
392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit	3	0
395.8(a)(1)	ELD - No record of duty status (ELD Required)	2	2
395.8	Record of Duty Status violation (general/form and manner)	6	0
393.55(c)(1)	Truck Tractor manufactured on or after March 1, 1997 not equipped with an antilock brake system	1	0
393.55(d)(2)	CMV manufactured on/after 3/1/2001 not equipped with ABS malfunction circuit / lamp from towed vehicle in cab	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	2	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
393.9(a)	Inoperable Required Lamp	1	0
393.11	Side retroreflective sheeting or reflex reflector requirements for vehicles manufactured after December 1993	4	0

Report executed at: 12/12/2024 12:18:28 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle	1	0
393.45(d)	Brake connections with leaks or constrictions	1	0
393.78	Wipers - Inoperative / missing / damaged wipers	1	0
393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	1	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001	1	0

The summary counts and rates only include violations that were attributable to ROJASECHEMENDIA, MICHAEL.

Report executed at: 12/12/2024 12:18:28 PM

MCMIS snapshot date: 11/29/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.