

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name		First Name			License #			State					
MOUTI		ABDERRAHIM			M300000640210			FL					
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		1	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		1	# of Towaways:		1		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		1	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	12/10/2019	1965782	US ADVANCE TRANSPORTATION INC	MOUTI, ABDERRAHIM	M300000640210	FL	01/21/1964	FL	FL8818853309	NB SR-91 (FL TURNPIKE) 60 MM	0	1	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		6		Vehicle Inspections:		1		Hazmat Inspections		0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:		0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:		0%			
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	01/13/2022	3179799	TRUCKING ALLIANCE LLC	MOUTI, ABDERRAHIM	M300000640210	FL	01/21/1964	FL	3507007794	N	3	0	

Report executed at: 1/14/2025 9:19:17 AM

MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	03/27/2022	3179799	TRUCKING ALLIANCE LLC	MOUTI, ABDERRAHIM	M300000640210	FL	01/21/1964	PA	E935208633	N	2	7
Vehicle Violation:		393.9(a)	Inoperable tail lamp			NON-OOS						
Vehicle Violation:		395.22(g)	Portable ELD not mounted in a fixed position and visible to driver			NON-OOS						
Vehicle Violation:		393.11	No or defective lighting devices or reflective material as required			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.78	Wipers - Inoperative / missing / damaged wipers			NON-OOS						
Vehicle Violation:		393.95(a)	No/discharged/unsecured fire extinguisher			NON-OOS						
Vehicle Violation:		393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition			NON-OOS						
3	01/08/2024	2446988	FOX TRUCKING LLC	MOUTI, ABDERRAHIM	M300000640210	FL	01/21/1964	NY	SPD0261892	N	3	3
Driver Violation:		395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)			NON-OOS						
Driver Violation:		395.3(a)(3)(i)	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)			NON-OOS						
Driver Violation:		395.3(a)(3)(i)	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)			NON-OOS						
4	02/28/2024	2446988	FOX TRUCKING LLC	MOUTI, ABDERRAHIM	M300000640210	FL	01/21/1964	CA	UE0F003682	N	3	1
Driver Violation:		392.2	Lane Restriction violation			NON-OOS						
5	07/26/2024	2446988	FOX TRUCKING LLC	MOUTI, ABDERRAHIM	M300000640210	FL	01/21/1964	AR	7850000265	N	3	0
6	10/21/2024	2945627	FOUR WAYS CARGO INC	MOUTI, ABDERRAHIM	M300000640210	FL	01/21/1964	WV	PSC1670546	N	3	0

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)	1	0
395.3(a)(3)(i)	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)	2	0
393.9(a)	Inoperable tail lamp	2	0
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0
393.11	No or defective lighting devices or reflective material as required	1	0
393.78	Wipers - Inoperative / missing / damaged wipers	1	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.47(a)	Inadequate brakes for safe stopping - Brake Lining condition	1	0
392.2	Lane Restriction violation	1	0

The summary counts and rates only include violations that were attributable to MOUTI, ABDERRAHIM.

Report executed at: 1/14/2025 9:19:17 AM

MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>