

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
CRUzMARTIN		FREDY		40122715		TX									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		3		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	07/13/2023	3788894	ARKO LLC	CRUZ MARTIN, FREDY	40122715	TX	01/28/1973	TX	V231080967	N	2	3			
Vehicle Violation:		393.45		Brake tubing and hose adequacy		NON-OOS									
Vehicle Violation:		393.78		Wipers - Inoperative / missing / damaged wipers		NON-OOS									
Vehicle Violation:		393.9(a)		Inoperable Required Lamp		NON-OOS									

Report executed at: 2/5/2025 12:38:50 PM

MCMIS snapshot date: 12/27/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	11/22/2023	3788894	ARKO LLC	CRUZ MARTIN, FREDY	40122715	TX	01/28/1973	TX	V231213143	N	2	1
Vehicle Violation:			393.11	No or defective lighting devices or reflective material as required			NON-OOS					
3	12/20/2023	3788894	ARKO LLC	CRUZ MARTIN, FREDY	40122715	TX	01/28/1973	TX	V231247764	N	2	2
Driver Violation:			392.2	Excessive Weight violation			NON-OOS					
Driver Violation:			392.2	Excessive Weight violation			NON-OOS					
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.11		No or defective lighting devices or reflective material as required							1			
392.2		Excessive Weight violation							2			
393.45		Brake tubing and hose adequacy							1			
393.78		Wipers - Inoperative / missing / damaged wipers							1			
393.9(a)		Inoperable Required Lamp							1			

The summary counts and rates only include violations that were attributable to CRUZMARTIN, FREDY.

Report executed at: 2/5/2025 12:38:50 PM

MCMIS snapshot date: 12/27/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.