

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
HUSSAIN	MIAN	hus904820	ND										
HUSSAIN	MIAN	055540883	GA										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		4		Vehicle Inspections:		3		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		33%		Hazmat Out-of-service Rate:				0%	
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	03/14/2022	3533870	015 LOGISTICS INC	HUSSAIN, MIAN	055540883	GA	11/11/1990	KY	CV42904030	N	2	1	
Vehicle Violation:		393.9(a)		Inoperative turn signal		OOS							

Report executed at: 2/11/2025 11:50:33 AM

MCMIS snapshot date: 01/31/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	02/07/2023	2293628	VIOR TRANSPORTATION INC	HUSSAIN, MIAN	hus904820	ND	11/11/1990	TX	6IEA0DUSQL	N	2	0
3	08/07/2023	2154824	S GROVER CONSTRUCTION INC	HUSSAIN, MIAN	hus904820	ND	11/11/1990	ND	TR04003122	N	2	9
Driver Violation: 392.82(a)(1) Using a hand-held mobile telephone while operating a CMV NON-OOS Driver Violation: 392.16(a) Failing to use seat belt while operating a CMV NON-OOS Vehicle Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998) NON-OOS Vehicle Violation: 393.95(a) No/discharged/unsecured fire extinguisher NON-OOS Vehicle Violation: 393.9(a) Inoperable tail lamp NON-OOS Vehicle Violation: 396.9(d)(2) Failure to correct defects noted on previous inspection report NON-OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 396.9(d)(2) Failure to correct defects noted on previous inspection report NON-OOS												
4	09/01/2023	2154824	S GROVER CONSTRUCTION INC	HUSSAIN, MIAN	hus904820	ND	11/11/1990	ND	TR04003155	N	3	1
Driver Violation: 392.82(a)(1) Using a hand-held mobile telephone while operating a CMV NON-OOS												

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.9(a)	Inoperative turn signal	2	1
392.82(a)(1)	Using a hand-held mobile telephone while operating a CMV	2	0
392.16(a)	Failing to use seat belt while operating a CMV	1	0
393.55(d)(1)	CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)	1	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
396.9(d)(2)	Failure to correct defects noted on previous inspection report	2	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0

The summary counts and rates only include violations that were attributable to HUSSAIN, MIAN.

Report executed at: 2/11/2025 11:50:33 AM

MCMIS snapshot date: 01/31/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>