

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																	
Last Name		First Name		License #			State										
GIMERANESPEREZ		LUIS		G565520732480			FL										
Crash Activity																	
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0			
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0			
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries					
Inspection Activity (3 year history from MCMIS snapshot date)																	
Inspection Summary																	
Driver Summary				Vehicle Summary				Hazmat Summary									
Driver Inspections:				1		Vehicle Inspections:				1		Hazmat Inspections				0	
Driver Out-of-service Inspections:				0		Vehicle Out-of-service Inspections:				1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:				0%		Vehicle Out-of-service Rate:				100%		Hazmat Out-of-service Rate:				0%	
Inspection Details																	
Carrier Info				Driver Info					Inspection Info								
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol					
1	09/24/2024	1554838	ARAPAHOE OILFIELD SERVICES LLC	GIMERANES PEREZ, LUIS	G565520732480	FL	07/08/1973	NM	654607G80D	N	2	2					
Vehicle Violation:		393.9(a)		Inoperative turn signal				OOS									
Driver Violation:		392.2		State/Local Laws - Speeding 6-10 miles per hour over the speed limit				NON-OOS									

Report executed at: 3/13/2025 1:22:44 PM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
393.9(a)	Inoperative turn signal	1	1
392.2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit	1	0

The summary counts and rates only include violations that were attributable to GIMERANESPEREZ, LUIS.

Report executed at: 3/13/2025 1:22:44 PM

MCMIS snapshot date: 02/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.