

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name			First Name			License #			State						
RUIZ			DAVID			22104766			TX						
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:			0			
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:			0			
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries				
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:				5		Vehicle Inspections:				2		Hazmat Inspections:		0	
Driver Out-of-service Inspections:				0		Vehicle Out-of-service Inspections:				1		Hazmat Out-of-service Inspections:		0	
Driver Out-of-service Rate:				0%		Vehicle Out-of-service Rate:				50%		Hazmat Out-of-service Rate:		0%	
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol				
1	08/27/2021	3054867	TEGA TRANSPORT INC	RUIZ JR, DAVID	22104766	TX	01/26/1988	OK	PE17001383	N	3	0			
2	09/01/2021	3054867	TEGA TRANSPORT INC	RUIZ JR, DAVID	22104766	TX	01/26/1988	MI	BEAMW02448	N	3	1			
Driver Violation: 392.2				State/Local Laws - Speeding 6-10 miles per hour over the speed limit.				NON-OOS							

Report executed at: 10/25/2022 1:37:31 PM

MCMIS snapshot date: 09/30/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

3	09/17/2021	3054867	TEGA TRANSPORT INC	RUIZ, DAVID	22104766	TX	01/26/1988	PA	E917126028	N	2	5
Driver Violation:	392.2	Failure to obey traffic control device	NON-OOS									
Driver Violation:	392.2	Miscellaneous Traffic Law Violation	NON-OOS									
Vehicle Violation:	393.95(a)	No/discharged/unsecured fire extinguisher	NON-OOS									
Vehicle Violation:	393.75(a)(1)	Tire-ply or belt material exposed	OOS									
Vehicle Violation:	393.75(a)(1)	Tire-ply or belt material exposed	OOS									
4	03/23/2022	3054867	TEGA TRANSPORT INC	RUIZ, DAVID	22104766	TX	01/26/1988	SC	D149005220	N	3	1
Driver Violation:	392.2	Dimension Violation (Width / Height / Length)	NON-OOS									
5	05/07/2022	3054867	TEGA TRANSPORT INC	RUIZ, DAVID	22104766	TX	01/26/1988	MO	W138004997	N	1	4
Driver Violation:	392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.	NON-OOS									
Vehicle Violation:	393.47(e)	Clamp or Roto type brake out-of-adjustment	NON-OOS									
Vehicle Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	NON-OOS									
Vehicle Violation:	396.3(a)(1)	Brakes (general) Explain:	NON-OOS									

#### Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	Failure to obey traffic control device	5	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.75(a)(1)	Tire-ply or belt material exposed	2	2
393.47(e)	Clamp or Roto type brake out-of-adjustment	1	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
396.3(a)(1)	Brakes (general) Explain:	1	0

The summary counts and rates only include violations that were attributable to RUIZ, DAVID.

Report executed at: 10/25/2022 1:37:31 PM

MCMIS snapshot date: 09/30/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>