

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
NEGRIN		NEGRIN		N265960842420			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		25%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	06/18/2021	2828543	ZIGI FREIGHT INC	NEGRIN, YUNIER	N265960842420	FL	07/02/1984	TN	TERC003197	N	2	1			
Vehicle Violation:		392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.				NON-OOS							

Report executed at: 8/25/2023 1:38:54 PM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	07/14/2021	2828543	ZIGI FREIGHT INC	YUNIER, NEGRIN	N265960842420	FL	07/02/1984	MS	5017100276	N	1	6
Vehicle Violation:		393.45(a)	Air Brake tubing improperly joined or spliced			OOS						
Vehicle Violation:		396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination			OOS						
Vehicle Violation:		393.47(e)	Clamp or Roto type brake out-of-adjustment			NON-OOS						
Vehicle Violation:		393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear			NON-OOS						
Vehicle Violation:		393.47(e)	Clamp or Roto type brake out-of-adjustment			NON-OOS						
Vehicle Violation:		393.47(e)	Clamp or Roto type brake out-of-adjustment			NON-OOS						
3	03/14/2022	3081779	US ROADWAY INC	NEGRIN, YUNIER	N265960842420	FL	07/02/1984	NV	7107018732	N	2	1
Vehicle Violation:		393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998			NON-OOS						
4	11/07/2022	3081779	US ROADWAY INC	NEGRIN, YUNIER	N265960842420	FL	07/02/1984	IA	000TT65RJ0	N	2	0

Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.								1	0		
393.45(a)	Air Brake tubing improperly joined or spliced								1	1		
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination								1	1		
393.47(e)	Clamp or Roto type brake out-of-adjustment								3	0		
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear								1	0		
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998								1	0		

The summary counts and rates only include violations that were attributable to NEGRIN, NEGRIN.

Report executed at: 8/25/2023 1:38:54 PM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>