

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information																							
Last Name		First Name		License #		State																	
DAVIS		WILLIAM		00340342		TX																	
Crash Activity																							
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																							
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0									
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0									
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries											
Inspection Activity (3 year history from MCMIS snapshot date)																							
Inspection Summary																							
Driver Summary				Vehicle Summary				Hazmat Summary															
Driver Inspections:				1				Vehicle Inspections:				0				Hazmat Inspections				0			
Driver Out-of-service Inspections:				0				Vehicle Out-of-service Inspections:				0				Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:				0%				Vehicle Out-of-service Rate:				0%				Hazmat Out-of-service Rate:				0%			
Inspection Details																							
Carrier Info				Driver Info						Inspection Info													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol											
1	10/19/2021	2591449	LOADSTAR LOGISTICS INC	DAVIS, WILLIAM	00340342	TX	11/11/1981	IN	7018007436	N	3	2											
Driver Violation:				392.2				State/Local Laws - Speeding work/construction zone.				NON-OOS											
Driver Violation:				395.22(g)				Portable ELD not mounted in a fixed position and visible to driver				NON-OOS											

Report executed at: 8/13/2023 2:25:46 PM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	State/Local Laws - Speeding work/construction zone.	1	0
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0

The summary counts and rates only include violations that were attributable to DAVIS, WILLIAM.

Report executed at: 8/13/2023 2:25:46 PM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.