

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #		State									
PIRONEAU		PIRONEAU		P650720821850		FL									
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		1		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		1	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
1	04/01/2020	2468544		ROBENS, PIRONEAU	P650720821850	FL	05/25/1982	NJ	NJ0020138672	DIVISION ST	0	0			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		8		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		12%		Vehicle Out-of-service Rate:		25%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	03/08/2021	3398095	U-FREIGHT INC	PIRONEAU, ROBENS	P650720821850	FL	05/25/1982	CO	PF29501650	N	2	2			
Driver Violation:		395.8(e)(1)		False report of drivers record of duty status				OOS							
Driver Violation:		395.26(b)		Motor carrier failed to ensure that the ELD automatically recorded the required data elements.				NON-OOS							

Report executed at: 8/14/2023 10:14:51 AM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

2	05/04/2021	3398095	U-FREIGHT INC	ROBENS, PIRONEAU	P650720821850	FL	05/25/1982	AZ	0223010380	N	2	0
3	08/03/2021	3182031	MID GROUP TRANSPORTATION INC	PIRONEAU, ROBENS	P650720821850	FL	05/25/1982	GA	1369001608	N	1	10
<div>Vehicle Violation: 396.3(a)(1) A liquid fuel system with a dripping leak at any point. OOS</div> <div>Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS</div> <div>Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS</div> <div>Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS</div> <div>Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS</div> <div>Vehicle Violation: 393.48(a) Inoperative/defective brakes OOS</div> <div>Vehicle Violation: 393.45(a) Air Brake tubing improperly joined or spliced OOS</div> <div>Vehicle Violation: 396.9(d)(2) Failure to correct defects noted on previous inspection report NON-OOS</div> <div>Vehicle Violation: 393.45(d) Brake Connections with Leaks - Connection to Power Unit NON-OOS</div> <div>Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS</div>												
4	09/21/2021	2305744	BLUE DOLPHIN TRANSPORT INC	PIRONEAU, ROBENS (co-driver)	P650720821850	FL	05/25/1982	MT	F637008663	N	3	0
5	12/01/2021	2305744	BLUE DOLPHIN TRANSPORT	PIRONEAU, ROBENS	P650720821850	FL	05/25/1982	PA	T204133596	N	3	1
Vehicle Violation: 392.2 Wheel (Mud) Flaps missing or defective NON-OOS												
6	06/24/2022	3737660	ZILLION LOGISTICS LLC	PIRONEAU, ROBENS	P650720821850	FL	05/25/1982	TN	TDON000221	N	3	1
Driver Violation: 392.2 Unlawfully parking and/or leaving vehicle in the roadway NON-OOS												
7	08/02/2022	3737660	ZILLION LOGISTICS LLC	PIRONEAU, ROBENS	P650720821850	FL	05/25/1982	LA	LANL004735	N	3	0
8	10/26/2022	2628863	BIG BOY CARRIERS LLC	PIRONEAU, ROBENS	P650720821850	FL	05/25/1982	TN	AUF1000102	N	1	2
<div>Vehicle Violation: 393.45(d) Brake Connections with Leaks - Connection to Power Unit NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS</div>												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		Unlawfully parking and/or leaving vehicle in the roadway							2		0	

Report executed at: 8/14/2023 10:14:51 AM

MCMIS snapshot date: 07/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.45(d)	Brake Connections with Leaks - Connection to Power Unit	2	0
393.9(a)	Inoperative turn signal	1	0
395.8(e)(1)	False report of drivers record of duty status	1	1
395.26(b)	Motor carrier failed to ensure that the ELD automatically recorded the required data elements.	1	0
396.3(a)(1)	A liquid fuel system with a dripping leak at any point.	2	2
393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	2	0
393.47(e)	Clamp or Roto type brake out-of-adjustment	1	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
393.48(a)	Inoperative/defective brakes	1	1
393.45(a)	Air Brake tubing improperly joined or spliced	1	1
396.9(d)(2)	Failure to correct defects noted on previous inspection report	1	0

The summary counts and rates only include violations that were attributable to PIRONEAU, PIRONEAU.

Report executed at: 8/14/2023 10:14:51 AM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.