

**Full Throttle Truck and Trailer  
Repair LLC.**

117 South Parkway  
Columbus, NE 68601  
aaron@puntneytruckingllc.com  
(402) 563-9199


**Invoice: INV-3230**
**Date: 7/9/2025**
**Bill To**

Royal 3 Inc  
6850 West 63rd Street  
Chicago, IL 60638  
P: (630) 405-7879

**Remit Payment To**

Full Throttle Truck and Trailer  
117 South Parkway  
Columbus, NE 68601

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
SO-3976	COD	7/9/2025	Eric		T01

Item	Description	Quantity	Rate	Amount
<b>Drive to unit</b>				
Labor	Drive to unit (Service Call) 6850 West 63rd Street, Chicago, IL - 2	1.25000	\$125.00	\$156.25
<b>Subtotal</b>				\$156.25

**Complaint:** Repair axle hub

**Cause:** Customer request

Labor	<b>Correction:</b> Trailer / Wheels / Inspected hub for reuse. Hub took damage when outer bearing seized and race broke loose and spun inside hub-recommend replace. Removed seized bearing trace from axle shaft, shaft has a lot of metal transfer from when race headed up and spun. Axle is bad-needs replaced. Abs Sensor damaged when Hub came loose. Axle nuts damaged, not reusable. Drum damaged-replace. Shoes soaked in grease-replace. Unable to 'repair' damages. Estimate replacement. - 3 - Created: 7/7/2025 Completed: 7/9/2025	5.00000	\$125.00	\$625.00
<b>Subtotal</b>				\$625.00

**Complaint:** Hub replacment

**Cause:** Customer request

(Inspection)

Item	Description	Quantity	Rate	Amount
Labor	<b>Correction:</b> Trailer / Wheels / Replaced hub and all associated parts after axle end was replaced by axle doctor. -new brake shoes -new drum -new axle nut kit -new hubcap gasket -new abs sensor -replaced 1/2 clevis's pin in Slack adjuster Reinstalled wheels and tires. Torqued to spec. Adjusted new brakes shoes. Complete. - 3 - Created: 7/8/2025 Completed: 7/9/2025	5.00000	\$125.00	\$625.00
Parts	4707 brake shoes	1.00000	\$48.29	\$48.29
Parts	Inherent Core for 4707 brake shoes	1.00000	\$47.15	\$47.15
Parts	Dirty Core for 4707 brake shoes	-1.00000	\$120.73	<b>-\$120.73</b>
Parts	Loaded hub	1.00000	\$290.92	\$290.92
Parts	1/2 CLEVIS PIN	1.00000	\$2.66	\$2.66
Parts	ABS Sensor Kit	1.00000	\$93.14	\$93.14
Parts	STEMCO FASTNER	1.00000	\$84.40	\$84.40
Parts	6 holeTrailer hub cap Gasket	1.00000	\$7.26	\$7.26
Parts	Brake Drum 16.50x7.0	1.00000	\$96.60	\$96.60
			<b>Subtotal</b>	\$1,174.69
<b>Return from unit</b>				
Labor	Return from unit 6850 West 63rd Street, Chicago, IL - 2	0.00000		\$0.00
			<b>Subtotal</b>	\$0.00
Replace Axle spindal		1.00	\$2,413.16	\$2,413.16
<b>Unit: T01 VIN: 1GRAP0620JT106138</b>			<b>Labor</b>	\$1,406.25
1988 Great Dane Trailers Great Dane Trailers			<b>Parts</b>	\$549.69
<b>Chassis: 1 Miles</b>			<b>Shop Supplies</b>	\$15.00
			<b>Pre-Charge Subtotal</b>	\$1,970.94
			<b>Replace Axle spindal</b>	\$2,413.16
			<b>Local</b>	\$163.78
			<b>(5.5% of \$2,977.85)</b>	
			<b>Total</b>	\$4,547.88
			<b>Payments &amp; Credits</b>	\$0.00
			<b>Balance Due</b>	\$4,547.88

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform

the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Date: \_\_\_\_\_