## DRIVER/VEHICLE EXAMINATION REPORT

Driver: Dominguez Jerez, Miguel

License# D55254186080

Date of Birth# 03/18/1986

State# IL

CoDriver:

License#

Date of Birth#

State#

Virginia	a State Pol

ce

Phone: (540) 387-5437 Fax: (804) 254-1635 Email/Web: mcsu2@vsp.virginia.gov

	Area 66	
2	D O Box 27472	

Richmond, VA 23261

Report Number: VA4233000444
Inspection Date: 07/30/2024
Start: 08:37 AM EDT End: 09:22 AM E
Inspection Level: 1
HM Inspection Type: None

Location: TROUTVILLE SCALES MilePost: 148.8 Highway: NB I-81 County: BOTETOURT Shipper: TIFTON QUALITY PEANUTS Bill of Lading: 013544 Origin: TIFTON, GA, US Destination: STUARTS DRAFT, VA, US Cargo: PEANUTS

## VEHICLE IDENTIFICATION

RIKI TRANSPORTATION INC

8225 LECLAIRE AVE

BURBANK, IL, 60459

USDOT#: 3119062

Phone#: 7083035150

dba: BRZ

MC/MX#:

State#:

Fax#:

GVWR Mileage CVSA # CVSA Issued # OOS Sticker Unit Type Make Year State Plate # Equipment ID VIN 34308781 1M1AN4GY6LM017939 53,200 53124 1 TT MACK 2020 IL P1238751 823 2 ST GDAN 2022 ME 451980Z W94928 1GR1P0626NJ324215 68,000

RAKE MEAS	UREMENT	S				
Steer Axle	Yes	No	No	No	No	
Chamber	Disc	Disc	Disc	CLAMP - 30-E	CLAMP - 30-E	
Right	N/A	N/A	N/A	1	1	
Axle	1	2	3	4	5	
Left	N/A	N/A	N/A	11/8	1 1/8	

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Via Cada	Section	Unit	OOS	Citation #	Verify	Violations Discovered
Vio Code 392 2-SLLMF	392.2	1	N		N	State/Local Laws - Wheel (mud) flaps missing or defective: LEFT REAR TRAILER MUDFLAP MISSING (46.2-1083 CODE OF VA)
393.55E-B	393.55(e)	2	N		N	Air Brake - ABS malfunction lamp defective on trailers manufactured on or after March 1, 1998: TRAILER ABS LIGHT INOP DOES NOT CYCLE ON/OFF

## Special Checks:

No Data for Special Checks.

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. False certifications of the required repairs are required to be prosecuted with penalties up to \$10,000.

Signature Of Repairer X:		Facility:	Date:
Report Prepared By: ATpr William B. Perry	<u>Badge #: Radio #:</u> 4233 1580	CODY Received By: MIGUEL A DOMINGUEZBER X	3119062 VA VA42330000444
Č	)		