

DRIVER/VEHICLE EXAMINATION REPORT



Wisconsin State Patrol - MGES
Southeast Region - Trip H
4822 Madison Yards Way, 9th Floor South
Madison, WI 53705-9100
Phone: (608) 267-9762 Fax: 608-583-1550
Email/Web: return reports to: safespect.dsp@dot.wi.gov (no reply)

Report Number: W12315000248
Inspection Date: 01/30/2025
Start: 04:22 PM CST End: 04:51 PM CST
Inspection Level: II Certification Date:
HM Inspection Type: None

RJK TRANSPORTATION INC
8225 LECLAIRE AVE
BURBANK, IL 60459
dba: BRZ
USDOT#: 3119062
MC/MX#: 1000000
State: IL
Phone#: 7083035150
Fax#: 7083035150

Driver: Velazquez, Luis, Manuel
License#: V422533882180
State: FL
Date of Birth: 06/18/1988
CoDriver:
License:
State:
Date of Birth:

Location: Franklin WI
MilePost:
Highway: 6467-6401 West Oakwood Road
County: Milwaukee County
Shipper:
Bill of Lading:
Origin: CHICAGO, IL, US
Destination: FRANKLIN, WI, US
Cargo: Empty

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	MACK	2022	IL	P1151481	831	1M1AN4GY0NM023464	53,200				
2	ST	GDAN	2022	ME	451991Z	W94939	1GR1P0620NJ324226	68,000				

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Via Code	Section	Unit	OOS	Citation #	Verify	Violations Discovered
345.04(2)	392.2	D	N		N	Disregarding traffic sign or signal: VEHICLE COMBO OBSERVED ON OAKWOOD EB; THEN TURNED NB ONTO 60TH ST. BOTH ROADS ARE POSTED 3 TON LIMIT.
393.9A-LRL1	393.9(a)	1	N		U	Lighting - Tail lamp - Any inoperative: LEFT/RIGHT TAIL-LAMPS ON TRACTOR ARE INOPERATIVE.

Special Checks:

Traffic Enforcement

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. False certifications of the required repairs are required to be prosecuted with penalties up to \$10,000.

Signature Of Repairer X: [Signature]

Total Quality Truck & Reefer Repair

Facility: [Signature]

Date: 1.31.25

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. [49 CFR 396.9(d)(1)]
NOTE TO MOTOR CARRIERS: All mechanical defects must be repaired before the vehicle is re-dispatched. This certification must be signed by the motor carrier and returned to the Wisconsin State Patrol via fax: 608-583-1550 or email: safespect.dsp@dot.wi.gov within 15 days. The motor carrier is also required to retain a copy for 12 months from the date of inspection. If a citation was issued, the bond amount should be mailed to the applicable county Clerk of Court. Requests for Data Review: <http://dataqs.fmcisa.dot.gov>

Signature Of Motor Carrier Official X: [Signature]

Date: 02/04/25

Report Prepared By:
Insp Matthew Kneisler

Badge #: 2315

Copy Received By:
LUIS MANUEL VELAZQUEZ

Page 1 of 1



3119062 WI W12315000248



Patrol - MCES
Southeast Region - Trp H
4822 Madison Yards Way, 9th Floor South
Madison, WI 53705-9100
Phone: (608) 267-9762 Fax: 608-583-1550
Email/Web: return reports to: safespect.dsp@dot.wi.gov (no reply)

EXAMINATION REPORT

Report Number: WI2315000248
Inspection Date: 01/30/2025
Start: 04:22 PM CST End: 04:51 PM CST
Inspection Level: II Certification Date:
HM Inspection Type: None

MOTOR CARRIER INFORMATION

RIKI TRANSPORTATION INC
8225 LECLAIRE AVE
BURBANK, IL, 60459
dba: BRZ
USDOT#: 3119062
MC/MX#:
State#:
Phone#: 7083035150
Fax#:

Driver: Velazquez, Luis, Manuel
License# V422533882180
State# FL
Date of Birth# 06/18/1988
CoDriver:
License#
State#
Date of Birth#

Location: Franklin WI
MilePost:
Highway: 6467-6401 West Oakwood Road
County: Milwaukee County
Shipper:
Bill of Lading:
Origin: CHICAGO, IL, US
Destination: FRANKLIN, WI, US
Cargo: Empty

STATE INFORMATION

General Info: Enter CFS#: 000303-1496
Axles: Axle 1 wt.: ; Axle Spacing 1 - 2: ; Axle 2 wt.: ; Axle Spacing 2 - 3: ; Axle 3 wt.: ; Axle Spacing 3 - 4: ; Axle 4 wt.: ; Axle Spacing 4 - 5: ; Axle 5 wt.: ; Axle Spacing 5 - 6: ; Axle 6 wt.: ; Axle Spacing 6 - 7: ; Axle 7 wt.: ; Axle Spacing 7 - 8: ; Weight - Axle 8: ; Additional Axles info.: ; Gross Axle wt.:
Permit Info: Permit Violation Detected: ; Permit #: ; Permitted Length: ; Measured Length: ; Permitted Height: ; Measured Height: ; Permitted Width: ; Measured Width: ;
Permitted Weight: ; Measured Weight:

Report Prepared By:
Inspector: [Signature]

Page 1 of 1

Copy Received By:
LUIS MANUEL VELAZQUEZ

Page 1 of 1



3119062 WI WI2315000248

INVOICE

Total Quality Truck & Reefer Repair,
LLC,
7320 W Florist Ave Ste 180
Milwaukee, WI 53218

totalqualitytruck@gmail.com
+1 (847) 909-4443



Bill to
BRZ RIKI TRANSPORTATION INC
8225 LECLAIRE AVE
BURBANK, IL 60459

Ship to
BRZ RIKI TRANSPORTATION INC
8225 LECLAIRE AVE
BURBANK, IL 60459

Invoice details

Invoice no.: 2179

Invoice date: 01/31/2025

Unit Number: 831

Vin: NM023464

#	Date	Product or service	SKU	Description	Qty	Rate	Amount
1.		Labor Electrical		Electrical Labor truck came in with back running lights, not working after diagnostic found corroded wire, which was broke off connected, check the lights it was working	175	\$125.00	\$218.75
2.		5th Wheel grease		5th Wheel grease PER DRIVER REQUEST	1	\$20.00	\$20.00
3.		operating supply		operating supply	1	\$10.375	\$10.38

Subtotal \$249.13

Sales tax \$1.58

Total \$250.71

Payment \$250.71

Balance due \$0.00

Thank You for your business we accepting Zelle payment as well:
totalqualitytruck@gmail.com

Note to customer

All tires must be tightened to a torque of 450 to 500 foot-pounds
within 50-100 miles