DRIVER/VEHICLE EXAMINATION REPORT Wisconsin State Patrol - MCES Report Number: WI2566000357 Northwest Region - Trp I Inspection Date: 04/07/2025 4822 Madison Yards Way, 9th Floor South start: 03:35 PM CDT End: 04:21 PM CDT Madison, WI 53705-9100 Inspection Level: II Certification Date: Phone: (608) 267-9762 Fax: 608-583-1550 -HM Inspection Type: None Email/Web: return reports to; safespect.dsp@dot.wi.gov (no reply) ZIGI FREIGHT INC Driver: Macdonald, Joseph, Edward Location: Hudson Wi 6850 W 63RD STREET License# M235485643410 MilePost: 8 CHICAGO, IL, 60639 State# FL Highway: Interstate 94 dba: ROYALSINC Date of Birth# 09/21/1964 County: St. Craix County USDOT#: 2828543 Shipper: MC/MX#: CoDriver: Bill of Lading: Statest License# Origin: COLD SPRING, MN, US Phone#: 6304857370 State# Destination: COLUMBIA, SC, US Date of Birth# Fax#: 6304856980 Cargo: BEER VEHICLE IDENTIFICATION Unit Type Make Year State Plate # Equipment ID VIN GVWR Mileage CVSA # CVSA Issued # OOS Sticker 1 TT FRHT 2021 IL P1095156 726 3AKJHHDRIMSMZ5508 52 500 2 ST GDAN 2022 ME 454509Z W97041 1GR1P0622ND335050 68.000 VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER Vio Code Section Unit oos Citation # Verify Violations Discovered State/Local Laws - Excessive weight - 1-2500 lbs over on an 392.2-SLLEWA1 392.2 N axle/axle groups: AXLS 2/3 WEIGHT = 34740 LBS/ LEGAL N WEIGHT = 34000 LBS/ OVERWEIGHT = 740 LBS. Tires - All others, leaking or inflation less than 50% of the 393.75A3-TAOL 393.75(a)(3) 2 V maximum inflation pressure on tire not equipped with ATIS: N AXL 5 LEFT INNER TIRE IS OFF THE BEAD, OPSI MAX 110 PSI. 393.78A-WS 393.78(a) N Washers - Inoperative washing system. : NO WASHER FLUID. N 393.9A-LLPL Lighting - License plate lamp inoperative: NOT WORKING. 393.9(a) N N DURING INSPECTION. Special Checks: E-Screening Technologies - Tire Screening, Pre-Clearance Systems - State System Pursuant to authority contained in Title 49, Code of Federal Regulations, Section 396.9(c), I hereby declare vehicles with defects followed by an "Y" in the "Out of Service" column in the violations discovered section of this report OUT OF SERVICE. No person shall remove the out of service stickers applied to these vehicles, or operate such vehicles until the out of service defects have been repaired and the vehicles have been restored to safe operating The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. False certifications of the required Signature Of Repairer X: " the and de Facility: NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. [49 CFR 396.9(d)(1)] NOTE TO MOTOR CARRIERS: All mechanical defects must be repaired before the vehicle is re-dispatched. This certification must be signed by the motor carrier and returned to the Wisconsin State Patrol via fax: 608-583-1550 or email: safespect.dsp@dot.wi.gov within 15 days. The motor carrier is also required to retain a copy for 12 months from the date of inspection. If a citation was issued, the bond amount should be mailed to the applicable county Signature Of Motor Carrier Official X: N4123125 Date: Report Prepared By: Insp Keigh C Wright Badge #: Copy Received By: 2566 JOSEPH EDWARD MACDONAL Page 1 of 1 2828543 WI WI2566000357