



FAMILY OWNED SINCE 1958



TRUCK COUNTRY -  
MILWAUKEE  
2222 W RYAN ROAD  
OAK CREEK, WI 53154

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

Warranty Customer Copy

THE REPAIRS LISTED BELOW ARE BEING SUBMITTED FOR WARRANTY CONSIDERATION  
WITH NO CURRENT CHARGES DUE FROM THE VEHICLE OWNER FOR THESE REPAIRS.

Owner:  
ZIGI FREIGHT DBA ROYAL3 INC  
6850 W 63RD STREET  
CHICAGO, IL 60638

Bill To:  
WARRANTY DETROIT  
1171  
DUBUQUE, IA 52001

WORK PHONE: (630)485-7370

HM PHONE: (872)401-1241

CUST#	&SWD	ADVISOR	6146	ENG	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#3 EA SWD (EA) DIAGNOSE AND ADVISE FOR

CLAIM NUMBER# **BWFD2025AG71T**

CONDITION (EA) DIAGNOSE AND ADVISE CUSTOMER STATES UNIT HAS COOLANT LEAK WHICH LOOKS LIKE ITS  
COMING FROM EGR

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: (EA) DIAGNOSE AND ADVISE CUSTOMER STATES UNIT HAS COOLANT LEAK  
WHICH LOOKS LIKE ITS COMING FROM EGR

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - COOLER, EGR / 043-001-079

CAUSE: LEAKING

PFP: DDE A4721400380

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

ATTACHMENTS:

ATTACHMENT COUNT: 1

NOTES/DIAGNOSTIC TIMES:

- PULL IN, PRESSURE TEST COOLING SYSTEM AND FOUND ONE LEAK AT REAR OF EGR COOLER  
MOUNTING SEAL. TOOK PIC AND ATTACHED. SENT PARTS REQUEST. MW  
101-018DE EGR COOLER EXTERNAL LEAK DIAGNOSTICS - DIFFICULT SH

NOTES/REPAIR TIMES:

101-6188G EGR COOLER, R/R, WITH STEAM CLEAN SH  
101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 963

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

00

GENERAL REPAIR

TECH NO. 2258

- 1203F/DDE A4721400480MOUNTINGSEAL,EGRCOOLER,FRONT
- 1203F/DDE A4721400380MOUNTING SEAL, EGR COOLER, REA
- 1203F/DDE A4721422880SEAL, EGR COOLER OUTLET ELBOW
- 1203F/DDE A0039950302CLAMP,EXHAUST,ML
- 1203F/DDE A0039957802CLAMP, EXHAUST, ML
- 2203F/DDE N000000001069SEALING RING, M14
- VMRS043-001-079-18-03-00-00

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#4 00 SWD GENERAL REPAIR

CLAIM NUMBER# **BWFD2025AG72T**

CONDITION CHECK AND ADVISE CUSTOMER STATES INJECTOR SEALS ARE LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE CUSTOMER STATES INJECTOR SEALS ARE LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - ADAPTER, FUEL INJECTOR LINES / 044-003-147

CAUSE: LEAKING

PFP: DDE A4720780180

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

ATTACHMENTS:

ATTACHMENT COUNT: 2

NOTES/DIAGNOSTIC TIMES:

- FOUND OIL ALL ON LEFT SIDE ENGINE. STEAM CLEAN ALL OIL OFF. BLOW DRY. SPRAY UP WITH MAGNA FLUX SPOT CHECK AND TOOK OUTSIDE, PUT IN REGEN, AFTER IT COMPLETED, PULL IN, INSPECT AND FOUND THREE OF THE FUEL INJECTOR LINE PASS THROUGH SEALS ARE LEAKING. SENT PARTS REQUEST. ATTACHED PICS. MW

101-010EE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - DIFFICULT SH

939-6225D COMPUTER HOOKUP USED IN VEHICLE DIAGNOSTICS SH

NOTES/REPAIR TIMES:

102-6222A LINE OR LINE SEAL, HIGH PRESSURE FUEL INJECTOR, ONE, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 963
00		GENERAL REPAIR	TECH NO. 2258
6	203F/DDE A4720780480	SEAL, FUEL INJECTOR LINE, PASS	
	VMRS	044-003-147-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#6 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG74T**

CONDITION CHECK AND ADVISE FRONT COVER IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FRONT COVER IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - FRONT COVER, LOWER / 045-001-020

CAUSE: LEAKING

PFP: DDE A4720110280

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010EE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - DIFFICULT GH

939-6225D COMPUTER HOOKUP USED IN VEHICLE DIAGNOSTICS GH

- PULLED UNIT INTO THE SHOP, INSPECTED FOR OIL LEAKS PER CUSTOMER COMPLAINT, STEAMED THE ENGINE, PULLED THE UNIT OUTSIDE THE SHOP, CONNECTED TO DL8, PLACED THE UNIT THROUGH A PARKED REGEN, STOPPED THE REGEN AFTER THIRTY MIN, APPLIED THE EMAGNAFLUX SPRAY, ALLOWED THE SPRAY TO DRY, CONFIRMED THERE ARE OIL LEAKS PRESENT AT THE FRONT COVER AND NUMEROUS OTHER LOCATIONS, UPDATED THE FOREMAN OF MY FINDINGS, REQUESTED PARTS NEEDED FOR THE REPAIRS, GH

NOTES/REPAIR TIMES:

101-6322E FRONT ENGINE COVER, LOWER, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2994
	00	GENERAL REPAIR	TECH NO. 2258
1	203D/LOC 37464	RTV 5699™ Grey High Performanc	
1	203F/DDE A4700111007	CRANKCASE COVER FRT	
1	203F/DDE A4720110380	MOUNTING GASKET, FRONT ENGINE	
1	203F/DDE A0169970646	OIL SEAL, CRANKSHAFT, FRONT	
1	203F/DDE A4730140122	SEAL, OIL PAN MOUNTING	
	VMRS	045-001-020-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#7 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG76T**

CONDITION CHECK AND ADVISE BLOCK FITTING IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE BLOCK FITTING IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: FITTING - BREATHER / 045-014-017

CAUSE: LEAKING

PFP: DDE A0049971371

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- breather fitting leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6855E FITTING, CRANKCASE BREATHER PIPE, R/R WITH STEAM CLEAN AND REPAIR VALIDATION

SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0079979271	SCREW-IN FITTING	
	VMRS	045-014-017-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#8 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG77T**

CONDITION CHECK AND ADVISE OIL BREATHER IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE OIL BREATHER IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - BREATHER ASSEMBLY, CRANKCASE VENTILATION / 045-014-008

CAUSE: LEAKING

PFP: DDE A4720180780

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- breather is leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6851E CRANKCASE BREATHER ASSEMBLY, R/R WITH STEAM CLEAN SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4720180780	GASKET, CRANKCASE BREATHER	
	VMRS	045-014-008-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#9 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG78T**

CONDITION CHECK AND ADVISE TURBO DRAIN PIPE IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE TURBO DRAIN PIPE IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: O-RING - OIL DRAIN TUBE, TURBOCHARGER / 043-004-173

CAUSE: LEAKING

PFP: DDE A0309974645

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- turbo drain at the block is leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

11A-6506E OIL RETURN LINE AND FITTINGS, TURBOCHARGER, R/R, WITH STEAM CLEAN AND REPAIR

VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4701870480	GASKET - TURBOCHARGER OIL DRAI	
1	203F/DDE A0309974645	O-RING, TURBOCHARGER OIL RETUR	
	VMRS	013-009-027-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#10 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG79T**

CONDITION CHECK AND ADVISE INJECTOR HARNESS IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE INJECTOR HARNESS IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: WIRING HARNESS - ELECTRONIC INJECTORS / 044-014-002

CAUSE: LEAKING

PFP: DDE A4721506233

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- front and rear injector harness leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

286-6105E HARNESS, FUEL INJECTOR WIRING, ONE OR BOTH, R/R WITH STEAM CLEAN SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4720160121	SEAL, ROCKER COVER	
1	203F/DDE A4721506333	WIRING HARNESS, FUEL INJECTOR,	
1	203F/DDE A4721506233	WIRING HARNESS, FUEL INJECTOR,	
	VMRS	044-014-002-18-03-00-00	



INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#11 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG80T**

CONDITION CHECK AND ADVISE CAM SENSOR IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE CAM SENSOR IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SENSOR - CAMSHAFT POSITION / 045-021-037

CAUSE: LEAKING

PFP: DDE A0071535928

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- cam sensor SH

- cam sensor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

283-6180A SENSOR, CAMSHAFT POSITION, R/R SH

101-6941E DETROIT REPAIR VALIDATION SH

939-6041A STEAM CLEAN, SPOT OF FAILURE SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0071535928	SENSOR, CAMSHAFT POSITION	
	VMRS	045-021-037-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#12 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG81T**

CONDITION CHECK AND ADVISE AIR COMPRESSOR IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE AIR COMPRESSOR IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: O-RING - AIR COMPRESSOR / 013-009-027

CAUSE: LEAKING

PFP: DDE A0309976645

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- air compressor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

107-6929F SEALS, AIR COMPRESSOR, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4722004751	LINE, COOLANT RETURN, ONE CYL	
1	203F/DDE A4722004651	LINE, COOLANT SUPPLY, ONE CYL	
1	203F/DDE A0309976645	OIL SUPPLY O-RING, AIR COMPRES	
1	203F/DDE A0239977145	O-RING, TOROIDAL SEALING, GEN	
1	203F/23-14393-000	UNION-PTC,.25 NT TO .25 NT	
1	203F/F4HZ 3K506 C	MOUNTING GASKET-POWER STEERING	
1	203D/OWI 23519396	COOLANT DDC PWRCOL ELC OAT 50/	
	VMRS	013-009-027-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#13 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG82T**

CONDITION CHECK AND ADVISE OIL PRESSURE SENSOR IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE OIL PRESSURE SENSOR IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SENSOR - ENGINE OIL PRESSURE / 045-021-029

CAUSE: LEAKING

PFP: DDE A0111539228

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- oil psi sensor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

283-6190E SENSOR, OIL PRESSURE, R/R WITH STEAM CLEAN SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE N000000001070	SEALING RING, M16	
1	203F/DDE A0111539228	SENSOR, OIL PRESSURE	
	VMRS	045-021-029-18-03-00-00	

INVOICE NO.	R203181134:01
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHDR3PSNM3949
UNIT	743

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#14 TCIOUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AG84T**

CONDITION CHECK AND ADVISE FRONT CAM CAPS ARE LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FRONT CAM CAPS ARE LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: PLUG - OIL GALLEY, CAMSHAFT / 045-008-004

POSITION: Front

CAUSE: LEAKING

PFP: DDE A4729980290

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- front cam frame galley plugs are leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6712A PLUG, CAMSHAFT HOUSING, FRONT, R/R, WITH STEAM CLEAN AND REPAIR VALIDATION

SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2258
2	203F/DDE A4729980290	PLUG, CAMSHAFT HOUSING, 40 MM	
	VMRS	045-008-004-18-03-01-00	

DISCLAIMER OF WARRANTIES ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND TRUCK COUNTRY OF Indiana NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF. TRUCK COUNTRY DOES EXPRESS A LIMITED NON-TRANSFERRABLE WARRANTY, TO THE ORIGINAL PURCHASER, ON TECHNICIAN WORKMANSHIP ISSUES FOR 30 DAYS FROM THE COMPLETION DATE OF THIS REPAIR ORDER. I ACKNOWLEDGE THAT I AM SATISFIED BY THE SERVICES PERFORMED IN REGARDS TO THESE CHARGES. RECEIVED  
BY:\_\_\_\_\_

SIGNATURE X \_\_\_\_\_