

TRUCK COUNTRY -MILWAUKEE 2222 W RYAN ROAD OAK CREEK, WI 53154

INVOIC	E NO.	R203181134:02					
INVOIC	E DATE	01/27/2025					
P.O. NI	P.O. NUMBER						
VIN	3AKJHH	DR3PSNM3949					
UNIT	743						

MILY OWNED SINCE 1958



Warranty Customer Copy

SH

THE REPAIRS LISTED BELOW ARE BEING SUBMITTED FOR WARRANTY CONSIDERATION WITH NO CURRENT CHARGES DUE FROM THE VEHICLE OWNER FOR THESE REPAIRS.

Owner: ZIGI FREIGHT DBA ROYAL3 INC 6850 W 63RD STREET CHICAGO, IL 60638

Bill To: WARRANTY DETROIT 1171 DUBUQUE, IA 52001

WORK PHONE: (630)485-7370 HM PHONE: (872)401-1241

	CUST#	&SWD	ADVISOR	6146	ENG	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
[YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#1 RECALL SWD CHECK FOR RECALL STICKER AND PERFORM RECALL PER ENCLOSED INSTRUCTION SHE

CLAIM NUMBER# BWFD2025AH56T

CONDITION CHECK FOR RECALL STICKER AND PERFORM RECALL PER ENCLOSED INSTRUCTION SHEET, INSTALL

COMPLETION STICKER ** D24M3 A - DRILLED EXHAUST ROCKER ARM INSTALLATION

CAUSE A1-CAMPAIGN

CORRECTION Techlane:

ORIGINAL COMPLAINT: CHECK FOR RECALL STICKER AND PERFORM RECALL PER ENCLOSED INSTRUCTION SHEET, INSTALL COMPLETION STICKER ** D24M3 A - DRILLED EXHAUST ROCKER ARM

INSTALLATION

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: ROCKER ARM - EXHAUST / 045-008-052

CAUSE: A1-CAMPAIGN PFP: DDE A4710500634

CORRECTION: DRILLED EXHAUST ROCKER ARM INSTALLATION, NO REPROGRAMMING (D24M3)

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: Scrap

NOTES/DIAGNOSTIC TIMES:

NOTES/REPAIR TIMES:

996-F179A DRILLED EXHAUST ROCKER ARM INSTALLATION, NO REPROGRAMMING (D24M3)

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE RA4720500633	KIT-OIL DRILLED ROCKER	
1	203F/DDE A4720160121	SEAL, ROCKER COVER	
(1)	203F/DDE RA4720500633-CORE	KIT-OIL DRILLED ROCKER	
1	203F/DDE RA4720500633-CORE	KIT-OIL DRILLED ROCKER	
	VMRS	045-008-052-A1-12-00-00	

INVOIC	CE NO.	R203181134:02			
INVOIC	E DATE	01/27/2025			
P.O. NUMBER					
VIN 3AKJHHDR3PSNM3949					
UNIT	743				

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

JOB#5 00 SWD GENERAL REPAIR

CLAIM NUMBER# BWFD2025AH57T

CONDITION CHECK AND ADVISE FOR CEL ON

CAUSE LOW PRESSURE

CORRECTION Techlane:

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR CEL ON

MODIFIED COMPLAINT: N/A

FAULT CODES:

ACM301T 520349/14 - DPF filter efficiency too low

STATUS: VERIFIED

PRIMARY FAILED COMPONENT: FILTER - DIESEL PARTICULATE, EXHAUST AFTER-TREATMENT DEVICES /

043-006-017

CAUSE: LOW PRESSURE PFP: DDE EA0024908392 CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

939-6225D COMPUTER HOOKUP USED IN VEHICLE DIAGNOSTICS SH

- trucks has code for 520349/14 dpf filter efficiency too low SH

NOTES/REPAIR TIMES: 246-6171E DPF, R/R SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: SPN 520349/FMI 14 — GHG21

STATUS: SUBMITTED

1 Turn ignition ON (key ON, engine OFF). - SH

2 Connect DiagnosticLink. - SH

3 Were other aftertreatment faults diagnosed or repaired during this service visit? - SH

3b No; go to step 4. - SH

5 Check the repair and fault code history on the truck. Were previous aftertreatment repairs completed or fault codes logged? - SH

5b No; go to step 6. - SH

6 Was this truck built and/or had its last DPF replacement before December 2022? - SH

6a Yes; DPF improvements have been made since the previous DPF was installed. Replace DPF. Verify repair. - SH

QTY ITEM	DESCRIPTION	TECHNICIAN
00	GENERAL REPAIR	TECH NO. 2258

203F/DDE A0049941645 SPRING NUT, DPF COVER

203F/DDE A0004921680 GASKET - PARTICULATE FILTER, E

INVOI	CE NO.	R203181134:02			
INVOI	E DATE	01/27/2025			
P.O. NUMBER					
VIN	3AKJHHDR3PSNM3949				
UNIT	743				

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

1 203F/DDE A0039955101 CLAMP - PARTICULATE FILTER CON

1 203F/DDE A0009957033 CLAMP, DPF V BAND, GATS 2.0

5 203F/DDE N910143006001 SCREW, M6X16

 1
 203F/DDE EA0024908392
 KIT, DPF AND CLAMPS, GATS 2.0

 (1)
 203F/DDE EA0024908392-CORE
 KIT, DPF AND CLAMPS, GATS 2.0

 1
 203F/DDE EA0024908392-CORE
 KIT, DPF AND CLAMPS, GATS 2.0

VMRS 043-006-017-51-03-G8-00

JOB#15 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2025AH58T

CONDITION CHECK AND ADVISE FUEL PUMP IS LEAKING

CAUSE LEAKING CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FUEL PUMP IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - INJECTION PUMP / 044-003-031

CAUSE: LEAKING PFP: DDE A0179978945 CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES: - fuel pump leaking SH

NOTES/REPAIR TIMES:

102-6233E SEAL, HIGH PRESSURE FUEL PUMP, R/R WITH STEAM CLEAN AND REPAIR VALIDATION

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0179978945	MOUNTING O-RING, HIGH PRESSURE	
1	203F/DDE A4720781210	KIT - HIGH PRESSURE FUEL LINE	
	VMRS	044-003-031-18-03-00-00	

SH

INVOI	CE NO.	R203181134:02			
INVOI	E DATE	01/27/2025			
P.O. NUMBER					
VIN	3AKJHHDR3PSNM3949				
UNIT	743				

CUST#	&SWD	ADVISOR	6146	ENGINE	472912S0929508	COLOR	GRN	SCHED	1/21/25	UNTID	734885
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	378451	INSVC	1/1/00	ACCT	CHG

DISCLAIMER OF WARRANTIES ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND TRUCK COUNTRY OF Indiana NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF. TRUCK COUNTRY DOES EXPRESS A LIMITED NON-TRANSFERRABLE WARRANTY, TO THE ORIGINAL PURCHASER, ON TECHNICIAN WORKMANSHIP ISSUES FOR 30 DAYS FROM THE COMPLETION DATE OF THIS REPAIR ORDER. I ACKNOWLEDGE THAT I AM SATISFIED BY THE SERVICES PERFORMED IN REGARDS TO THESE CHARGES. RECEIVED BY:

SIGNATURE X