



FAMILY OWNED SINCE 1958



TRUCK COUNTRY -
MILWAUKEE
2222 W RYAN ROAD
OAK CREEK, WI 53154

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

Warranty Customer Copy

THE REPAIRS LISTED BELOW ARE BEING SUBMITTED FOR WARRANTY CONSIDERATION
WITH NO CURRENT CHARGES DUE FROM THE VEHICLE OWNER FOR THESE REPAIRS.

Owner:
ZIGI FREIGHT INC.
6850 W 63RD ST
CHICAGO, IL

Bill To:
WARRANTY DETROIT
1171
DUBUQUE, IA 52001

WORK PHONE: (773)290-4761

HM PHONE:

CUST#	&SWD	ADVISOR	6546	ENG	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

JOB#1 EXPRESS SWD (EA) DIAGNOSE AND ADVISE CONDITION

CLAIM NUMBER# **BWFD2025AJ47T**

CONDITION (EA) DIAGNOSE AND ADVISE CONDITION ** AIR COMPRESSOR LEAKING OIL
CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: (EA) DIAGNOSE AND ADVISE CONDITION ** INJECTOR SEALS ARE LEAKING

MODIFIED COMPLAINT: (EA) DIAGNOSE AND ADVISE CONDITION ** AIR COMPRESSOR LEAKING OIL

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: O-RING - AIR COMPRESSOR / 013-009-027

CAUSE: LEAKING

PFP: DDE A0239977145

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010EE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - DIFFICULT GH

939-6225D COMPUTER HOOKUP USED IN VEHICLE DIAGNOSTICS GH

- PULLED UNIT INTO THE SHOP, INSPECTED FOR OIL LEAKS PER CUSTOMER COMPLAINT, STEAMED
THE ENGINE, PULLED THE UNIT OUTSIDE THE SHOP, CONNECTED TO DL8, PLACED THE UNIT IN A PARKED
REGEN, STOPPED THE REGEN AFTER THIRTY MIN, APPLIED THE MAGNAFLUX SPRAY, ALLOWED THE
SPRAY TO DRY, FOUND THE REAR CAM PLUGS LEAKING ALONG OTHER COMPONENTS ON THE
ENGINE, GH

NOTES/REPAIR TIMES:

107-6929F SEALS, AIR COMPRESSOR, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SP

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 2994
	00	GENERAL REPAIR	TECH NO. 5355
1	203F/DDE A0309976645	OIL SUPPLY O-RING, AIR COMPRES	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

1 203F/DDE A0239977145 O-RING, TOROIDAL SEALING, GEN
1 203F/F4HZ 3K506 C MOUNTING GASKET-POWER STEERING
1 203F/23-14393-000 UNION-PTC,.25 NT TO .25 NT
1 203D/OWI 23519396 COOLANT DDC PWRCOL ELC OAT 50/
1 203F/DDE A4722004651 LINE, COOLANT SUPPLY, ONE CYL
1 203F/DDE A4722004751 LINE, COOLANT RETURN, ONE CYL
VMRS 013-009-027-18-03-00-00

JOB#4 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2025AJ48T

CONDITION CHECK AND ADVISE TURBO DRAIN PEIPE IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE TURBO DRAIN PEIPE IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - TURBOCHARGER OIL DRAIN TUBE / 043-004-071

CAUSE: LEAKING

PFP: DDE A4701870480

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SP

NOTES/REPAIR TIMES:

11A-6506E OIL RETURN LINE AND FITTINGS, TURBOCHARGER, R/R, WITH STEAM CLEAN AND REPAIR

VALIDATION SP

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 5355
1	203F/DDE A4701870480	GASKET - TURBOCHARGER OIL DRAI	
1	203F/DDE A0309974645	O-RING, TURBOCHARGER OIL RETUR	
	VMRS	043-004-071-18-03-00-00	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

JOB#5 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AJ49T**

CONDITION CHECK AND ADVISE OIL BREATHER IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE OIL BREATHER IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: BREATHER ASSEMBLY - CRANKCASE VENTILATION / 045-014-006

CAUSE: LEAKING

PFP: DDE EA4720108262

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SP

NOTES/REPAIR TIMES:

101-6851E CRANKCASE BREATHER ASSEMBLY, R/R WITH STEAM CLEAN SP

101-6941E DETROIT REPAIR VALIDATION SP

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 5355
1	203F/DDE A4720180780	GASKET, CRANKCASE BREATHER	
1	203F/DDE EA4720108262	BREATHER ASSEMBLY - CRANKCASE	
1	203F/DDE A0071535928	SENSOR, CAMSHAFT POSITION	
1	203F/DDE EA4720108262-CORE	BREATHER ASSEMBLY - CRANKCASE	
	VMRS	045-014-006-18-03-00-00	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

JOB#6 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AJ50T**

CONDITION CHECK AND ADVISE BLOCK FITTING IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE BLOCK FITTING IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: FITTING - BREATHER / 045-014-017

CAUSE: LEAKING

PFP: DDE A0079979271

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SP

NOTES/REPAIR TIMES:

101-6855E FITTING, CRANKCASE BREATHER PIPE, R/R WITH STEAM CLEAN AND REPAIR VALIDATION
SP

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 5355
1	203F/DDE A0079979271	SCREW-IN FITTING	
	VMRS	045-014-017-18-03-00-00	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

JOB#7 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AJ52T**

CONDITION CHECK AND ADVISE OIL PRESSURE SENSOR IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE OIL PRESSURE SENSOR IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SENSOR - ENGINE OIL PRESSURE / 045-021-029

CAUSE: LEAKING

PFP: DDE A0111539228

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SP

NOTES/REPAIR TIMES:

283-6190E SENSOR, OIL PRESSURE, R/R WITH STEAM CLEAN SP

101-6941E DETROIT REPAIR VALIDATION SP

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 5355
1	203F/DDE N000000001070	SEALING RING, M16	
1	203F/DDE A0111539228	SENSOR, OIL PRESSURE	
	VMRS	045-021-029-18-03-00-00	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

JOB#10 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AJ53T**

CONDITION CHECK AND ADVISE CAM SENSOR IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE CAM SENSOR IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SENSOR - CAMSHAFT POSITION / 045-021-037

CAUSE: LEAKING

PFP: DDE A0071535928

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SP

NOTES/REPAIR TIMES:

283-6180A SENSOR, CAMSHAFT POSITION, R/R SP

101-6941E DETROIT REPAIR VALIDATION SP

939-6041A STEAM CLEAN, SPOT OF FAILURE SP

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 5355
1	203F/DDE A0071535928	SENSOR, CAMSHAFT POSITION	
	VMRS	045-021-037-18-03-00-00	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

JOB#11 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AJ54T**

CONDITION CHECK AND ADVISE FUEL PUMP IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FUEL PUMP IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - INJECTION PUMP / 044-003-031

CAUSE: LEAKING

PFP: DDE A0179978945

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SP

NOTES/REPAIR TIMES:

102-6233E SEAL, HIGH PRESSURE FUEL PUMP, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SP

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 5355
1	203F/DDE A4720781210	KIT - HIGH PRESSURE FUEL LINE	
1	203F/DDE A0179978945	MOUNTING O-RING, HIGH PRESSURE	
	VMRS	044-003-031-18-03-00-00	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

JOB#12 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AJ55T**

CONDITION CHECK AND ADVISE REAR CAM PLUGS ARE LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE REAR CAM PLUGS ARE LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: PLUG - OIL GALLEY, CAMSHAFT / 045-008-004

POSITION: Rear

CAUSE: LEAKING

PFP: DDE A4729980290

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SP

NOTES/REPAIR TIMES:

101-6712B PLUG, CAMSHAFT HOUSING, REAR, R/R WITH STEAM CLEAN AND ROAD TEST SP

TECHLIT PROCEDURES:

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 5355
1	203F/DDE A4720160880	MOUNTING SEAL, CAMSHAFT HOUSIN	
3	203F/DDE A4729980290	PLUG, CAMSHAFT HOUSING, 40 MM	
6	203F/DDE A4720780480	SEAL, FUEL INJECTOR LINE, PASS	
1	203F/23-12240-058	SPACER-AL.,.375 ID.75 O	
	VMRS	045-008-004-18-03-55-00	

INVOICE NO.	R203181326:01
INVOICE DATE	01/30/2025
P.O. NUMBER	
VIN	3AKJHHDR7PSUA1616
UNIT	773

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0998572	COLOR	GRN	SCHED	1/28/25	UNTID	768481
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	343310	INSVC	1/1/00	ACCT	CHG

DISCLAIMER OF WARRANTIES ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND TRUCK COUNTRY OF Indiana NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF. TRUCK COUNTRY DOES EXPRESS A LIMITED NON-TRANSFERRABLE WARRANTY, TO THE ORIGINAL PURCHASER, ON TECHNICIAN WORKMANSHIP ISSUES FOR 30 DAYS FROM THE COMPLETION DATE OF THIS REPAIR ORDER. I ACKNOWLEDGE THAT I AM SATISFIED BY THE SERVICES PERFORMED IN REGARDS TO THESE CHARGES. RECEIVED

BY:_____

SIGNATURE X _____