



FAMILY OWNED SINCE 1958



TRUCK COUNTRY -  
MILWAUKEE  
2222 W RYAN ROAD  
OAK CREEK, WI 53154

INVOICE NO.	R203180817:02
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHFG7NSNM4000
UNIT	735

Warranty Customer Copy

THE REPAIRS LISTED BELOW ARE BEING SUBMITTED FOR WARRANTY CONSIDERATION  
WITH NO CURRENT CHARGES DUE FROM THE VEHICLE OWNER FOR THESE REPAIRS.

Owner:  
ZIGI FREIGHT DBA ROYAL3 INC  
6850 W 63RD STREET  
CHICAGO, IL 60638

Bill To:  
WARRANTY CUMMINS  
1170  
DUBUQUE, IA 52001

WORK PHONE: (630)485-7370

HM PHONE: (872)401-1241

CUST#	&SWC	ADVISOR	6546	ENG	80384233	COLOR	BLK	SCHED	1/10/25	UNTID	734871
YEAR	22	MAKE	FTL	MODEL	PT126	MILES	385643	INSVC	1/1/00	ACCT	CHG

JOB#1 EXPRESS SWC (EA) DIAGNOSE AND ADVISE CONDITION

CLAIM NUMBER# 16909528

CONDITION (EA) DIAGNOSE AND ADVISE CONDITION CEL, OUTLET NOX SENSOR FAULT

CAUSE \*\*\*sent email need tracking 1.20\*\*\*FAILED DIFFERENTIAL PRESSURE SENSOR GUIDANZ #01183959

CORRECTION BROUGHT UNIT INTO THE SHOP. CONFIRMED THAT THE CEL IS ON. WENT TO CONNECT TO INSITE AND FOUND THAT INSITE LICENSING WAS HAVING AN ISSUE. GOT WITH ASSISTANT MANAGER. HAD I.T. WORKING ON COMPUTER FOR FIRST PUNCH TIME. CHECKED DPF PRESSURE TUBES FOR KINKS OR LEAKS. NONE FOUND. REMOVED THE TURBES. NO SIGNS OF PLUGGING. BLEW THROUGH WITH AIR GUN. NO PLUGGING IN EITHER TUBE. REINSTALLED BOTH TUBES. TORQUED TO SPEC. CODE IS CURRENTLY ACTIVE. PER T/S UNIT WILL NEED A NEW DPF DIFFERENTIAL PRESSURE SENSOR. PUT IN A PARTS REQUEST. ADVISED FOREMAN. removed and replaced dpf differential pressure sensor. tried to hook up laptop to unit but insite isnt working. used another techs laptop and hooked up and performed fault verification. cleared inactive faults. test drove vehicle and parked vehicle back in lot. returned part to warranty cart. completed guidanz for aftertreatment fault.

QTY	ITEM	DESCRIPTION	TECHNICIAN
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 3260
	00	GENERAL REPAIR	TECH NO. 5163
	00	GENERAL REPAIR	TECH NO. 5163
	00	GENERAL REPAIR	TECH NO. 5163
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 3260
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 3260
1	203C/5492073	SENSOR,DFN PRESSURE	
12	203F/PHM 8 43147	TIE STRAP-14.5IN,BLACK,NYLON,5	

INVOICE NO.	R203180817:02
INVOICE DATE	01/24/2025
P.O. NUMBER	
VIN	3AKJHHFG7NSNM4000
UNIT	735

CUST#	&SWC	ADVISOR	6546	ENGINE	80384233	COLOR	BLK	SCHED	1/10/25	UNTID	734871
YEAR	22	MAKE	FTL	MODEL	PT126	MILES	385643	INSVC	1/1/00	ACCT	CHG

DISCLAIMER OF WARRANTIES ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND TRUCK COUNTRY OF Indiana NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF. TRUCK COUNTRY DOES EXPRESS A LIMITED NON-TRANSFERRABLE WARRANTY, TO THE ORIGINAL PURCHASER, ON TECHNICIAN WORKMANSHIP ISSUES FOR 30 DAYS FROM THE COMPLETION DATE OF THIS REPAIR ORDER. I ACKNOWLEDGE THAT I AM SATISFIED BY THE SERVICES PERFORMED IN REGARDS TO THESE CHARGES. RECEIVED  
BY:\_\_\_\_\_

SIGNATURE X \_\_\_\_\_