



FAMILY OWNED SINCE 1958



TRUCK COUNTRY -  
MILWAUKEE  
2222 W RYAN ROAD  
OAK CREEK, WI 53154

INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

Warranty Customer Copy

THE REPAIRS LISTED BELOW ARE BEING SUBMITTED FOR WARRANTY CONSIDERATION  
WITH NO CURRENT CHARGES DUE FROM THE VEHICLE OWNER FOR THESE REPAIRS.

Owner:  
ZIGI FREIGHT DBA ROYAL3 INC  
6850 W 63RD STREET  
CHICAGO, IL 60638

Bill To:  
WARRANTY DETROIT  
1171  
DUBUQUE, IA 52001

WORK PHONE: (630)485-7370

HM PHONE: (872)401-1241

CUST#	&SWD	ADVISOR	6546	ENG	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#2 EXPRESS SWD (EA) DIAGNOSE AND ADVISE CONDITION

CLAIM NUMBER# **BWFD2025AA58T**

CONDITION (EA) DIAGNOSE AND ADVISE CONDITION COOLANT LEAK FROM EGR COOLER.

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: (EA) DIAGNOSE AND ADVISE CONDITION COOLANT LEAK FROM EGR COOLER.

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - COOLER, EGR / 043-001-079

CAUSE: LEAKING

PFP: DDE A4721400380

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-018DE EGR COOLER EXTERNAL LEAK DIAGNOSTICS - DIFFICULT ID  
- PULLED UNIT INTO SHOP. FOUND COOLANT AROUND EGR COOLER. PRESSURE TESTED COOLING  
SYSTEM AND FOUND BOTH FRONT AND REAR EGR COOLER SEALS ARE LEAKING. REMOVED  
PRESSURE TESTER. SENT IN PARTS REQUEST FOR NECESSARY PARTS TO COMPLETE REPAIR.  
PARKED UNIT IN LOT. INFORMED FOREMAN OF FINDINGS. ID

NOTES/REPAIR TIMES:

101-6188G EGR COOLER, R/R, WITH STEAM CLEAN SH  
101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 6322
	00	GENERAL REPAIR	TECH NO. 2258
2	203F/DDE N000000001069	SEALING RING, M14	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

1 203F/DDE A4721400480 MOUNTINGSEAL,EGRCOOLER,FRONT  
1 203F/DDE A4721400380 MOUNTING SEAL, EGR COOLER, REA  
VMRS 043-001-079-18-03-00-00

JOB#4 EA SWD (EA) DIAGNOSE AND ADVISE FOR

CLAIM NUMBER# **BWFD2025AA59T**

CONDITION (EA) DIAGNOSE AND ADVISE FOR INJECTOR SEALS LEAKING.

CAUSE LEAKING

CORRECTION Techlane :  
ORIGINAL COMPLAINT: (EA) DIAGNOSE AND ADVISE FOR INJECTOR SEALS LEAKING.

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - ADAPTER, FUEL INJECTOR LINES / 044-003-147

CAUSE: LEAKING

PFP: DDE A4720780180

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- all pass through seals leaking SH  
101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

102-6222A LINE OR LINE SEAL, HIGH PRESSURE FUEL INJECTOR, ONE, R/R WITH STEAM CLEAN AND

REPAIR VALIDATION SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 2258
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 2258
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 2258
6	203F/DDE A4720780480	SEAL, FUEL INJECTOR LINE, PASS	
	VMRS	044-003-147-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#6 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA61T**

CONDITION check and advise for front cover leaking

CAUSE LEAKING

CORRECTION Techlane :  
ORIGINAL COMPLAINT: check and advise for front cover leaking

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - FRONT COVER, LOWER / 045-001-020

CAUSE: LEAKING

PFP: DDE A4720110280

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010EE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - DIFFICULT GH  
- PULLED UNIT INTO THE SHOP, INSPECTED FOR OIL LEAKS PER CUSTOMER COMPLAINT, STEAMED THE ENGINE, PULLED THE UNIT OUTSIDE THE SHOP, CONNECTED TO DL8, PLACED THE UNIT THROUGH A PARKED REGEN, STOPPED THE REGEN AFTER THIRTY MIN, APPLIED THE MAGNAFLUX SPRAY, ALLOWED THE SPRAY TO DRY, CONFIRMED THERE ARE OIL LEAKS PRESENT AT THE FRONT COVER, BREATHER BLOCK FITTING, THE OIL SEP, THE TURNO DRAIN PIPE, THE OPS, THE FUEL PUMP, THE AIR COMP, AND THE REAR CAM PLUGS, UPDATED THE FOREMAN, REQUESTED PARTS NEEDED FOR THE REPAIRS, GH  
939-6225D COMPUTER HOOKUP USED IN VEHICLE DIAGNOSTICS GH

NOTES/REPAIR TIMES:

101-6322E FRONT ENGINE COVER, LOWER, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2994
	00	GENERAL REPAIR	TECH NO. 2258
1	203D/LOC 37464	RTV 5699™ Grey High Performanc	
1	203F/DDE A4700111007	CRANKCASE COVER FRT	
1	203F/DDE A4720110380	MOUNTING GASKET, FRONT ENGINE	
1	203F/DDE A0169970646	OIL SEAL, CRANKSHAFT, FRONT	
1	203F/DDE A4730140122	SEAL, OIL PAN MOUNTING	
	VMRS	045-001-020-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#7 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA62T**

CONDITION CHECK AND ADVISE FOR BLOCK FITTING LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR BLOCK FITTING LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: FITTING - BREATHER / 045-014-017

CAUSE: LEAKING

PFP: DDE A0049971371

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- breather fitting leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6855E FITTING, CRANKCASE BREATHER PIPE, R/R WITH STEAM CLEAN AND REPAIR VALIDATION

SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0079979271	SCREW-IN FITTING	
	VMRS	045-014-017-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#8 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA63T**

CONDITION CHECK AND ADVISE FOR FOR OIL BREATHER IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR FOR OIL BREATHER IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - BREATHER ASSEMBLY, CRANKCASE VENTILATION / 045-014-008

CAUSE: LEAKING

PFP: DDE A4720180780

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- oil separator leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6851E CRANKCASE BREATHER ASSEMBLY, R/R WITH STEAM CLEAN SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4720180780	GASKET, CRANKCASE BREATHER	
	VMRS	045-014-008-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#9 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA64T**

CONDITION CHECK AND ADVISE FOR TURBO DRAIN TUBE IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR TURBO DRAIN TUBE IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: O-RING - OIL DRAIN TUBE, TURBOCHARGER / 043-004-173

CAUSE: LEAKING

PFP: DDE A0309974645

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- turbo drain tube at the block leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

11A-6506E OIL RETURN LINE AND FITTINGS, TURBOCHARGER, R/R, WITH STEAM CLEAN AND REPAIR

VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4701870480	GASKET - TURBOCHARGER OIL DRAI	
1	203F/DDE A0309974645	O-RING, TURBOCHARGER OIL RETUR	
	VMRS	043-004-173-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#10 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA65T**

CONDITION CHECK AND ADVISE FOR OIL PRESSURE SENSOR LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR OIL PRESSURE SENSOR LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SENSOR - ENGINE OIL PRESSURE / 045-021-029

CAUSE: LEAKING

PFP: DDE A0111539228

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: RETURN (RETURN ALL PARTS)

NOTES/DIAGNOSTIC TIMES:

- oil psi sensor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

283-6190E SENSOR, OIL PRESSURE, R/R WITH STEAM CLEAN SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE N000000001070	SEALING RING, M16	
1	203F/DDE A0111539228	SENSOR, OIL PRESSURE	
	VMRS	045-021-029-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#11 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA66T**

CONDITION CHECK AND ADVISE FOR FUEL PUMP IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR FUEL PUMP IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - INJECTION PUMP / 044-003-031

CAUSE: LEAKING

PFP: DDE A0179978945

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- fuel pump is leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

102-6233E SEAL, HIGH PRESSURE FUEL PUMP, R/R WITH STEAM CLEAN AND REPAIR VALIDATION

SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0179978945	MOUNTING O-RING, HIGH PRESSURE	
1	203F/DDE A4720781210	KIT - HIGH PRESSURE FUEL LINE	
	VMRS	044-003-031-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#12 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA67T**

CONDITION CHECK AND ADVISE FOR AIR COMPRESSOR IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR AIR COMPRESSOR IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: O-RING - AIR COMPRESSOR / 013-009-027

CAUSE: LEAKING

PFP: DDE A0309976645

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- air compressor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

107-6929F SEALS, AIR COMPRESSOR, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0309976645	OIL SUPPLY O-RING, AIR COMPRES	
1	203F/DDE A0239977145	O-RING, TOROIDAL SEALING, GEN	
1	203F/F4HZ 3K506 C	MOUNTING GASKET-POWER STEERING	
1	203F/23-14393-000	UNION-PTC,.25 NT TO .25 NT	
1	203F/DDE A4722004651	LINE, COOLANT SUPPLY, ONE CYL	
1	203F/DDE A4722004751	LINE, COOLANT RETURN, ONE CYL	
1	203D/OWI 23519396	COOLANT DDC PWRCOL ELC OAT 50/	
	VMRS	013-009-027-18-03-00-00	
	C	CAN ALSO USE 4988280	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#13 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA68T**

CONDITION CHECK AND ADVISE FOR REAR CAM PLUGS ARE LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FOR REAR CAM PLUGS ARE LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: PLUG - OIL GALLEY, CAMSHAFT / 045-008-004

POSITION: Rear

CAUSE: LEAKING

PFP: DDE A4729980290

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- rear cam cap leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

- pulled the cam frame off and found the front galley plugs are leaking as well . sent in a request for more galley plugs. r/r the front galley plugs SH

101-6712B PLUG, CAMSHAFT HOUSING, REAR, R/R WITH STEAM CLEAN AND ROAD TEST SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2994
00		GENERAL REPAIR	TECH NO. 2258
5	203F/DDE A4729980290	PLUG, CAMSHAFT HOUSING, 40 MM	
1	203F/DDE A4720160880	MOUNTING SEAL, CAMSHAFT HOUSIN	
1	203F/DDE A4720160121	SEAL, ROCKER COVER	
	VMRS	045-008-004-18-03-55-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#14 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA69T**

CONDITION CHECK AND ADVISE IDLER GEAR COVER IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE IDLER GEAR COVER IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - COVER, ADJUSTABLE IDLER GEAR / 045-004-036

CAUSE: LEAKING

PFP: DDE A0002361880

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- idler cover on the rear structure leaking

SH

NOTES/REPAIR TIMES:

101-6510E GASKET, COVER, IDLER GEAR #3 R/R SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0002361880	GASKET, IDLER 3 COVER PLATE	
	VMRS	045-004-036-18-03-00-00	



INVOICE NO.	R203180623:01
INVOICE DATE	01/09/2025
P.O. NUMBER	
VIN	3AKJHHDR2PSNM3957
UNIT	757

CUST#	&SWD	ADVISOR	6546	ENGINE	472912S0929429	COLOR	GRN	SCHED	1/3/25	UNTID	734893
YEAR	23	MAKE	FTL	MODEL	PT126	MILES	232061	INSVC	1/1/00	ACCT	CHG

JOB#15 TCIOUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2025AA70T**

CONDITION CHECK AND ADVISE INJECTOR HARNESS IS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE INJECTOR HARNESS IS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: WIRING HARNESS - ELECTRONIC INJECTORS / 044-014-002

CAUSE: LEAKING

PFP: DDE A4721506233

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- front and rear injector harness leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

286-6105E HARNESS, FUEL INJECTOR WIRING, ONE OR BOTH, R/R WITH STEAM CLEAN SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
00		GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4721506333	WIRING HARNESS, FUEL INJECTOR,	
1	203F/DDE A4721506233	WIRING HARNESS, FUEL INJECTOR,	
	VMRS	044-014-002-18-03-00-00	

DISCLAIMER OF WARRANTIES ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND TRUCK COUNTRY OF Indiana NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF. TRUCK COUNTRY DOES EXPRESS A LIMITED NON-TRANSFERRABLE WARRANTY, TO THE ORIGINAL PURCHASER, ON TECHNICIAN WORKMANSHIP ISSUES FOR 30 DAYS FROM THE COMPLETION DATE OF THIS REPAIR ORDER. I ACKNOWLEDGE THAT I AM SATISFIED BY THE SERVICES PERFORMED IN REGARDS TO THESE CHARGES. RECEIVED

BY:\_\_\_\_\_

SIGNATURE X \_\_\_\_\_