



5914 SO. Doug Andrus Rd.
IDAHO FALLS, ID 83402
P: (208) 497-3840
F: (208) 552-1380
www.mountainwesttrucks.com

SERVICE ORDER: RA104003313

ESTIMATE: 19445783

Tag Number:
Unit #: MP2162

BILL TO
BRZ TRUCKING - 36563
6850 W 63RD ST
CHICAGO IL 60835
P: (502) 905-2561

DELIVER TO
BRZ TRUCKING - 36563
6850 W 63RD ST
CHICAGO IL 60835
P: (502) 905-2561

DATE ARRIVED		DATE INVOICE	EXT COLOR	SALES TYPE	ADVISOR	TERMS	CUSTOMER PO#
3/27/2025 12:15:00PM				SR	K.BERRETT	CASH	
YEAR	MAKE	MODEL	VIN	ODOMETER IN	ODOMETER OUT	IN SERVICE	Component Serial #
2022	MACK	AN64T	1M1AN4GY7NM023462	417783	417783		

Sold Operations

JOB #1 ASIST DEFAULT ASIST/DECISIV - JOB

COMPLAINT CHECK 22 INSPECTION -
CAUSE

CORRECTION PREFORMED CHECK 22 INSPECTION AND FOUND THE FAN BELT HAS WEAR FROM RUBBING THE DAVCO FUEL FILTER FUEL LINES THE DRIVE LINE IS DISCONNECTED AND THE SLIP YOKE WAS PULLED OUT AND THE DRIVE LINE WILL NEED TO BE TIMED. NO OTHER ISSUES OR FAULTS FOUND AT THIS TIME. CHECK 22 COMPLETE.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR ASIST	CHECK 22 INSPECTION		0.00

JOB #1 Totals Prepay: \$0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 \$0.00

JOB #2 ASIST DEFAULT ASIST/DECISIV - JOB

COMPLAINT SC0472 - Bendix ABS ECU -
CAUSE AUTHORIZED BY DSM JIM BURKE

CORRECTION PREFORMED SCO472 BENDIX ABS ECU UPDATE. PULLED THE TRUCK INTO THE SHOP AND PLUGGED INTO THE BENDIX EC-80 ECU UPDATE TOOL. RAN THE SOFTWARE UPDATE, SOFTWARE UPDATED SUCCESSFULLY WITH NO ISSUES OR CHECK ENGINE LIGHT, SC0472 BENDIX ABS ECU CAMPAIGN RECALL COMPLETE.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR ASIST	SC0472 - Bendix ABS ECU		

JOB #2 Totals

**Sold Operations (Cont.)****JOB #3 ASIST DEFAULT ASIST/DECISIV - JOB**

COMPLAINT NO START -

CAUSE

CORRECTION CUSTOMER STATES NO START. TRUCK WAS TOWED IN INSPECTED THE FUEL FILTERS AND FOUND THEY ARE NEW. WHEN INSPECTING THE DAVCO FILTER FOUND THE FAN BELT LOOKED FUNNY LIKE IT WAS RUBBING ON SOMTHING AND NOTICED THE DAVCO FUEL LINES WERE RIGHT BY THE TENSIONER. INSPECTED THE FUEL LINES AND FOUND A NEW ZIPTIE HOLDING THE LINES FROM RUBBING THE BELT. AND THE FUEL LINES WERE RUBBED THROUGH AND CAUSING THE FUEL LINES TO SUCK AIR INTO THE FUEL. CUSTOMER APPROVED REPAIRS, DISCONNECTED THE FUEL LINES AND REMOVED THE FUEL LINES FROM THE TRUCK. INSTALLED THE NEW FUEL LINE AND SECURED THEM TO INSURE THEY WOULD NOT GET DAMAGED INSTALLED NEW FITTING ON BOTH ENDS OF BOTH FUEL LINES MADE SURE THE FITTINGS CLICKED INTO PLACE. FILLED THE DAVCO FILTER WITH FUEL AND PRIMED THE FUEL SYSTEM, STARTED THE TRUCK AND THE TRUCK STAYED RUNNING. INSPECTED THE FUEL LINE FOR LEAKS WITH NONE PRESENT. THE TRUCK DID HAVE A CHECK ENGINE LIGHT ON. PLUGGED IN TO PTT AND FOUND IT WAS LOW FUEL PRESSURE CODES. CLEARED THE CODES AND STARTED THE TRUCK WITH NO CODES RETURNING. REPAIR COMPLETE.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
35	104V/8071095	TUBE	7.08	247.80
4	104V/20395036	FITTING	17.48	69.92
1	FRT	NDA FREIGHT	200.00	200.00
	LABOR ASIST	NO START		525.00

JOB #3 Totals Prepay: \$0.00 Parts: \$317.72 Labor: \$525.00 Misc: \$200.00 Sublet: \$0.00 \$1,042.72

JOB #4 ASIST DEFAULT ASIST/DECISIV - JOB

COMPLAINT INSTALL DRIVE LINE, TOW-IN -

CAUSE

CORRECTION CUSTOMER STATES INSTALL DRIVE LINE. CUSTOMER WAS TOWED IN AND THE DRIVE LINE WAS DISCONNECTED, WHEN TRUCK WAS DROPPED OFF THE DRIVE LINE WAS SEPARATED AT THE SLIP YOKE AND NEEDED TO BE TIMED WHEN INSTALLED. TURNED THE DRIVE LINE AND LINED UP THE YOKES AND INSTALLED THE SLIP YOKE INTO THE FRONT HALF OF THE DRIVE LINE AND THEN INSTALLED THE DRIVE LINE BACK ONTO THE DIFF WITH NEW STRAPS AND BOLTS TORQUED BOLTS TO SPEC INSTALL OF DRIVE LINE COMPLETE.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	104V/85144661	KIT	46.19	46.19
	LABOR ASIST	INSTALL DRIVE LINE, TOW-IN		175.00

JOB #4 Totals Prepay: \$0.00 Parts: \$46.19 Labor: \$175.00 Misc: \$0.00 Sublet: \$0.00 \$221.19



SERVICE ORDER: RA104003313

ESTIMATE: 19445783

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Customer agrees to pay reasonable attorney fees and costs of collection. A service charge of 1 1/2% per month (A.P.R. = 18%) will be added to all accounts over 30 days past due.

DISCLAIMER OF WARRANTIES

Any warranties on the products sold hereby are those made by the manufacturer. MOUNTAIN WEST TRUCK CENTER hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and MOUNTAIN WEST TRUCK CENTER neither assumes nor authorizes any other person to assume for it any liability in connection with this sale.

	ESTIMATED	BILLED
LABOR		\$700.00
PARTS		\$363.91
MISC		\$200.00
SUBLET		\$0.00
Prepay		\$0.00
SUBTOTAL		\$1,263.91
SHOP SUPPLIES		\$70.00
MISC SUPPLIES		\$0.00
TAX		\$0.00
TOTAL		\$1,333.91

Please Remit Payment to:

MOUNTAIN WEST TRUCK CENTER

PO BOX #25117

SALT LAKE CITY, UT, 84125

ar@mountainwesttc.com

X

SIGNATURE OF PERSON RESPONSIBLE OR AGENT FOR PERSON RESPONSIBLE FOR PAYMENT.