



Advantage Truck Raynham, LLC

501 Paramount Drive
Raynham, MA 02767

Phone: (508) 925-4466: Parts - 1; Service - 2; Sales - 3

Fax: (508) 925-4462

RaynhamService@AdvantageTruckNE.com

Eight Convenient Locations or Online at AdvantageTruckNE.com

MA: Raynham, Shrewsbury & Westfield NH: Lancaster, Lebanon, Manchester & Seabrook VT: Westminster



BILL TO
ROYAL 3 - 68918
6850 W63 RD ST
BEDFORD PARK IL 60638
P: (630) 485-2570

DELIVER TO
ROYAL 3 - 68918
6850 W63 RD ST
BEDFORD PARK IL 60638
P: (630) 485-2570

SERVICE ORDER: R210007676

DATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE			
5/9/2025 2:30:25PM		SRET	A. MORALES	CASH				
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2023	FTL	PT126SLP	3AKJHHDR1PSNM3951	754	0	5/23/2022	472912S0926137	434835

Sold Operations

JOB #1 02 EXPRESS ASSESSMENT

COMPLAINT CUSTOMER STATES NO CRANK NO START

- *1231/14-POWERTRAIN CAN SHORT DETECTED
- *625/9- ACM PT-CAN MESSAGE IS MISSING

CAUSE
CORRECTION THE VEHICLE INITIALLY HAD A NO CRANK NO START ISSUE, WHICH WAS DIAGNOSED TO BE CAUSED BY A WIRING HARNESS FAULT IN THE ENGINE CONTROL ASSEMBLY. THE WIRING HARNESS WAS FOUND TO BE CUT OR RUBBED, LEADING TO A CAN SHORT TO BATTERY FAULT. THE DAMAGED WIRE WAS IDENTIFIED AS CIRCUIT 62AH PT CAN HIGH, LOCATED APPROXIMATELY 3 FEET FROM THE CONNECTOR ENG_CTRL_ENG_O_ECU_MCM_1A. THE REPAIR INVOLVED CUTTING AWAY CHAFE TAPE, REPAIRING THE WIRING, AND ENSURING PROPER RESISTANCE AND VOLTAGE LEVELS IN THE PTCAN SYSTEM. THE REPAIR OPERATION WAS COVERED UNDER WARRANTY, AND THE AFFECTED PARTS WERE DISPOSED OF.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02	DIAGNOSTIC		
1	210D/PAC 12186167 B	TUBING-HEAT SHRINK,63.5MM,7.62		
10	210D/PHM 8 44147	TIE STRAP-15IN BLACK,NYLON, *D		
1	210X/006	ELECT. CONNECTOR		

JOB #2 74 UNIT TOWED IN - INSPECT ALL REMOVED

COMPLAINT UNIT TOWED IN - FROM FRONT

CAUSE
CORRECTION INSPECTED UNDERCARGAGE, CHECKED DRIVESHAFT, REPLACED DRIVE SHAFT BOLTS AND TORQUED NEW BOLTS TO 120 FT POUNDS.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
4	210D/23-12891-175	SCREW-SOCKETHEAD 12PT,1/2-20,1	2.37	9.48
	LABOR 74	UNIT TOWED IN - INSPECT ALL REMOVED		120.00

Subtotals: Prepay: 0.00 Parts: \$9.48 Labor: \$120.00 Misc: \$0.00 Sublet: \$0.00

\$129.48



Sold Operations (Cont.)

JOB #3 71 QUALITY CHECK
COMPLAINT QUALITY CHECK
POC: JOSH 630-566-0552
maintenance@royal3inc.com

CAUSE
CORRECTION

Table with 5 columns: QTY, ITEM, DESCRIPTION, UNIT PRICE, EXTD PRICE. Row 1: LABOR 71, QUALITY CHECK, 0.00

Subtotals: Prepay: 0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 \$0.00

JOB #4 73 NON-WARRANTY ITEMS / DEDUCTIBLE

COMPLAINT NON-WARRANTY ITEMS / DEDUCTIBLE
CAUSE
CORRECTION

Table with 5 columns: QTY, ITEM, DESCRIPTION, UNIT PRICE, EXTD PRICE. Row 1: 1, 210X/BK A807124 NAP, SCENT, 15.09, 15.09. Row 2: LABOR 73, NON-WARRANTY ITEMS / DEDUCTIBLE, 200.00

Subtotals: Prepay: 0.00 Parts: \$15.09 Labor: \$200.00 Misc: \$0.00 Sublet: \$0.00 \$215.09

Sold Operations Subtotals Prepay: 0.00 Parts: \$24.57 Labor: \$320.00 Misc: \$0.00 Sublet: \$0.00 \$344.57

ESTIMATES VALID FOR 30 DAYS FROM DATE OF DOCUMENT. DISCLAIMER OF WARRANTIES: TRI STATE TRUCK CENTER, INC. MAKES NO ASSUMPTION OF WARRANTY FOR ANY PARTS, LABOR OR PREVIOUS REPAIRS PERFORMED AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON OR PERSONS TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THIS SALE.

Table with 3 columns: ESTIMATED, BILLED. Rows: LABOR (\$320.00), PARTS (\$24.57), MISC (\$0.00), SUBLET (\$0.00), PREPAY (0.00), SUBTOTAL (\$344.57)

Table with 2 columns: Description, Amount. Rows: SHOP SUPPLIES (\$25.60), MISC SUPPLIES (\$0.00), TAX (\$3.14), FINAL TOTAL (\$373.31)

NOT AN INVOICE

AUTHORIZED BY _____ DATE _____

PRINTED NAME _____

