



Invoice

Work Order #022 356893

I-84 EXIT 71

Page 1

MORE: BAYS. EXPERTISE. SOLUTIONS.

THANK YOU AND STAY SAFE!

Service Dept Manager:

327 RUBY RD.

WILLINGTON, CT 06279- (860) 684-0499

DOMINIC M CUTAIA 860-684-0499

For Questions or Concerns:

Company Name ROYAL3 INC			Driver's Name DRIVER CELL# 786-690-9191			ID		License		# 022 356893	
Address 6850 W 63RD STREET			CHK Pymt. Type 1874101365			Card # 78.35		PO # 0		Authorized by 531675	
City CHICAGO			State IL			Zip 60638		Written 11/02/23		20:30	
Tractor # 766			Year 20			Make/Model FTL CASCADIA		License # P1177712		PA	
Trailer # 305796			Year 00			Make/Model		License #		Hubodometer	
Work Requested UNIT SVCD: TRAILER			REYNALDO REQUESTS: CO: 630-405-7879			22:00		C/A TRAILER L/F/O TIRE FOR REPAIR IF POSSIBLE CO2: 630-485-7370			

SERVICE	PLU #	PART NUMBER	DESCRIPTION	UOM	REG. PRICE	PRICE	QTY	EXTENDED AMOUNT	
SL	997 002	SAP # 0001605126	SHOP SUPPLY/ENVIRONMENTAL FEE	EA	4.17	4.17	1.00	4.17	
SL	998 004	LABOR, SAP #0001606877	MECHANICAL HOURLY LABOR	HR	138.99	138.99	.50	69.50	
Please come again! Your feedback matters. Tell us about your visit at www.tafeedback.com .									
Customer agrees the only service work being requested by Customer from TA at this time is the work specifically listed in this work order. Customer understands TA offers additional services upon request; however, Customer declines any additional services not specifically listed on this work order. Customer hereby releases TA from any claims or liability related to service work, conditions and/or issues on Customer's vehicle/trailer which is not specifically listed in the work order, including, but not limited to, any inspection, evaluation or recommendation related to tires, component parts or other items not specifically identified in this work order.									
AMOUNT TENDERED:								78.35	
Parts :	0.00	New Tires :	0.00	Total :	73.67	Non-taxable :	0.00	ENV/WST Tax:	0.00
Labor :	73.67	Used Tires :	0.00	Discount :	0.00	Taxable :	73.67	TOTAL ► \$	78.35
Oil :	0.00	Trade-In :	0.00	Net :	73.67	Tax :	4.68	CHANGE RETURNED:	0.00

Technician Comments
FOUND AUTO INFLATOR HOSE ON TRAILER LFO TIRE WAS LOSE ENOUGH TO ALLOW THE FLOW OF AIR OUT OF THE TIRE,, TIGHTENED TO SPEC AND FOUND THAT AIR IS NOT LEAKING AT THIS TIME,, TWS,,

Remarks

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs therein.	Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or any other cause beyond our control.
*** NO SIGNATURE ON FILE ***	In the event that you, the customer, authorize commencement but do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work. Such charges will be directly related to the actual amount of labor or parts involved in the inspection, repair or service.