

## Invoice

## Work Order #251 132106

I-40 EXIT 170

Page

1670 US 601 #100

MOCKSVILLE, NC 27028- (336) 751-3815

ERIC P GRONDWALSKI 336-751-3815

For Questions or Concerns:

MORE: BAYS. EXPERTISE. SOLUTIONS. THANK YOU AND STAY SAFE!

Service Dept Manager:

License 251 132106 DRIVER CELL# 8183141485 Company Name NATHAN CORDEIRO TRIP# ROYAL3 INC 01335G Authorized by Card # \*XXXXXXXXXXXXXXXX313 302.80 PO# 6850 W 63RD STREET Written by jr0 ks hm City 11/11/23 09:57 11/11/23 08:42 11/11/23 08:36 11/11/23 06:23 60638 IL CHICAGO Engine Make/Model OTHER NM025545 IL 289500 P1110716 22 MAK ANTHEM 705 MARK AUTH#: 705 30004 5003254 MA VANGUARD но3236 24

Work Requested

NATHAN CORDEIRO REQUESTS:

NEEDS THE RFO TRAILER TIRE MOUNTED ON NEW WHEEL.

UNIT SUCD: TRAILER

PLEASE CHECK TIRE FOR ANY DAMAGE BEFORE MOUNTING

COMPANY # 630.566.1266 MARK

REF# 705 AUTH MARK

MARK.W@ROYAL3INC.COM								
SERVICE	PLU#	PART NUMBER	DESCRIPTION	UOM	REG. PRICE	PRICE	QTY	EXTENDED AMOUNT
TMOO	11.0#		TIRE MOUNT INSIDE/OUTSIDE				1.00	47.99
TMOO		CHECK NUT TORQUE BETWEEN 50-1	0 MILES OF OPERATION AFTER W	HEEL	1 1			
TMOO		SERVICE AS RECOMMENDED BY ATA-	TMC, NWRA, AND TRUCK OF MANU	FACTURERS.	1 . 1		e.	
TMOO	997 050	997 50, SAP #0001605250	STANDARD SERVICE LABOR B	HR	1		.10	
TMOO	998 002	77777, SAP #0001606876	STANDARD SERVICE LABOR	HR			. 90	
SL	587 024	VH727MS, SAP #0001123043	TRUCK TIRE VLV TR572 STRAIG	Hr EA	7.14	7.14	1.00	
SL	558 032	ACC 51408PKWHT21	22.5 HUB PILOT STEEL WHEEL	EA	212.46	212.46	1.00	212.46
		SAP #0001606129						
SL	997 002	SAP # 0001605126	SHOP SUPPLY/ENVIRONMENTAL F	EE EA	16.06	16.06	1.00	16.06
		Please come again! Your feed!  Customer agrees the only serv: specifically listed in this we request; however, Customer decorder. Customer hereby release and/or issues on Customer's ve including, but not limited to component parts or other items	ce work being requested by ork order. Customer understable clines any additional service ses TA from any claims or limelical claims or limelical control of the control of	customer from the customer fro	om TA at this ers additional ifically liste ated to servic y listed in the	time is the services up d on this wo e work, conce work order	on rk itions	
						AMOUNT	TENDERED	302.80
73 m m 4	. 219.	60 New Tires : 0.00	Total : 283.65 No	n-taxable :	0.00	ENV/WS	Tax:	0.00
Parts		New IIIes .		xable :	283.65	TOTAL	▶ \$	302.80
Labor		00 Trade-In : 0.00		×	19.15	CHANGE	RETURNED	

Technician Comments

DRIVER CAME IN FOR C/A ON REPLACING WHEEL ON RF. R EMOVED WHEEL FOUND CURVED OVER, REPLACED WITH NEW WHEEL, MOUNTED TIRE BACK TO AXLE, CHECKED FOR ANY DAMAGE, NONE FOUND, AIRED TO 100 PSI, STILL NO DAM THANKS KS

AGE FOUND. MOUNTED BACK TO RF AT 475 FT LBS

Remarks

croby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees mission to operate the vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged above vehicle to secure the amount of repairs therein.

Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or any other cause beyond our

In the event that you, the customer, authorize commencement but do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work. Such charges will be directly related to the actual amount of labor or parts involved in the inspection, repair or service.

ADDITIONAL REMARKS

VISA \*XXXXXXXXXXXXX1313

PUR INV 251100

Sales Total:

302.80 Auth#: 01335G

TID#: H837047300001

APPROVED