



Invoice

Work Order #139 334152

12403 US RT. 35

Page 1

MORE: BAYS. EXPERTISE. SOLUTIONS.

THANK YOU AND STAY SAFE!

JEFFERSONVILLE, OH 43128 (740) 948-2365

For Questions or Concerns:

Service Dept Manager:

RICHARD KNISLEY 740-948-2365

Company Name ROYAL3 INC			Driver's Name DRIVER CELL# 7088008072			ID		License		# 139 334152	
Address 6850 W 63RD STREET			MARCO TRIP#								
City CHICAGO			State IL			Zip 60638			Written 08/26/23		
Tractor # 749			Year 23			Make/Model FTL CASCADIA			License # P1150993 IL		
Trailer # H03252			Year 00			Make/Model			License #		
Work Requested UNIT SVCD: TRAILER			MARCO REQUESTS: CB# 630-566-0552			C/A LRI TIRE ON TRL JOSH AUTH TO REPAIR TIRE, CALL BACK IF NEEDS REPLA			CED		

SERVICE	PLU #	PART NUMBER	DESCRIPTION	UOM	REG. PRICE	PRICE	QTY	EXTENDED AMOUNT
SL	587 044	111	ULTRA 2.5RD 111	WH EA	4.73	4.73	1.00	4.73
SL	587 020	251/38-1	3/8 UNISEAL 251-3/8-1 20/1	EA	5.46	5.46	1.00	5.46
TMFI			OTH FLAT REPAIR (INSIDE WHEEL)				1.00	54.99
TMFI			LABOR ONLY. REPAIR MATERIAL NOT INCLUDED.					
TMFI			CHECK NUT TORQUE SPEC BETWEEN 50-100 MILES OF OPERATION AFTER WHEEL					
TMFI			SERVICE AS RECOMMENDED BY ATA-TMC, NWRA, AND TRUCK OE MANUFACTURERS.					
TMFI	997 050	997 50	STANDARD SERVICE LABOR B	HR			.10	
TMFI	998 002	777777	STANDARD SERVICE LABOR	HR			.60	
SL	587 699	0	CUSTOMER REFUSED VALVE STEM	EA	0.00	0.00	1.00	0.00
SL	997 002		SHOP SUPPLY/ENVIRONMENTAL FEE	EA	3.91	3.91	1.00	3.91
Please come again! Your feedback matters. Tell us about your visit at www.tafeedback.com .								
Customer agrees the only service work being requested by Customer from TA at this time is the work specifically listed in this work order. Customer understands TA offers additional services upon request; however, Customer declines any additional services not specifically listed on this work order. Customer hereby releases TA from any claims or liability related to service work, conditions and/or issues on Customer's vehicle/trailer which is not specifically listed in the work order, including, but not limited to any inspection, evaluation or recommendation related to tires, component parts or other items not specifically identified in this work order.								
AMOUNT TENDERED:								74.10
Parts :	10.19	New Tires :	0.00	Total :	69.09	Non-taxable :	0.00	ENV/WST Tax: 0.00
Labor :	58.90	Used Tires :	0.00	Discount :	0.00	Taxable :	69.09	TOTAL ► \$ 74.10
Oil :	0.00	Trade-In :	0.00	Net :	69.09	Tax :	5.01	CHANGE RETURNED: 0.00

Technician Comments DRIVER STATES LRI TRLR FLAT REQUEST C/A. FOUND BOL T STUCK IN TREAD ROUGHLY 1 AND 1/4 AWAY FROM SIDE WALL, WAS ABLE TO REPAIR WITH 2 PIECE PLUG CHECKED FOR LEAK ONCE REAIRED IN CAGE THERE WASNT A LEAK AT THE PLUG. RISK PROCESS FOLLOWED TIRE AIRED TO 1 00 PSI ALL LUGS AND STUDS OILED TORQUED TO 475 FT LBS. DRIVER WITNESSED TORQUE

Remarks

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs therein.

Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or any other cause beyond our control.

In the event that you, the customer, authorize commencement but do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work. Such charges will be directly related to the actual amount of labor or parts involved in the inspection, repair or service.

*** NO SIGNATURE ON FILE ***

ADDITIONAL REMARKS

VISA XXXXXXXXXXXX3461

Sales Total: 74.10 Auth#: 080615

APPROVED

PUR INV 139252

TID#: H839046277001

x 