



FAMILY OWNED SINCE 1958



TRUCK COUNTRY -
MILWAUKEE
2222 W RYAN ROAD
OAK CREEK, WI 53154

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

Warranty Customer Copy

THE REPAIRS LISTED BELOW ARE BEING SUBMITTED FOR WARRANTY CONSIDERATION
WITH NO CURRENT CHARGES DUE FROM THE VEHICLE OWNER FOR THESE REPAIRS.

Owner:
ZIGI FREIGHT DBA ROYAL3 INC
6850 W 63RD STREET
CHICAGO, IL 60638

Bill To:
WARRANTY DETROIT
1171
DUBUQUE, IA 52001

WORK PHONE: (630)485-7370

HM PHONE: (872)401-1241

CUST#	&SWD	ADVISOR	6675	ENG	COLOR	GRN	SCHED	11/8/24	UNTID	716963	
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#1 EA SWD (EA) DIAGNOSE AND ADVISE FOR

CLAIM NUMBER# **BWFD2024EP59T**

CONDITION (EA) DIAGNOSE AND ADVISE FOR UNIT HAS OIL LEAKS ON DRIVER SIDE OF ENGINE FUEL PUMP
CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: (EA) DIAGNOSE AND ADVISE FOR UNIT HAS OIL LEAKS ON DRIVER SIDE OF
ENGINE

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - INJECTION PUMP / 044-003-031

CAUSE: LEAKING

PFP: DDE A0179978945

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

101-010EE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - DIFFICULT GH

939-6225D COMPUTER HOOKUP USED IN VEHICLE DIAGNOSTICS GH

- PULLED UNIT INTO THE SHOP, VISUALLY INSPECTED FOR OIL LEAKS, STEAMED THE ENGINE, PULLED
THE UNIT OUTSIDE THE SHOP, CONNECTED TO DL8, PLACED THE UNIT IN A PARKED REGEN, STOPPED
THE REGEN AFTER THIRTY, APPLIED THE MAGNAFLUX SPRAY AND ALLOWED TO DRY, CONFIRMED THE
FUEL PUMP GASKET IS LEAKING, GH

NOTES/REPAIR TIMES:

102-6233E SEAL, HIGH PRESSURE FUEL PUMP, R/R WITH STEAM CLEAN AND REPAIR VALIDATION

SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	EXP	(EA) DIAGNOSE AND ADVISE FOR	TECH NO. 2994
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0179978945	MOUNTING O-RING, HIGH PRESSURE	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE	COLOR	GRN	SCHED	11/8/24	UNTID	716963	
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

1 203F/DDE A0000701432 FUEL LINE KT
2 203X/SIL 5089 BRAKLEEN
4 203F/DDE N000000001067 SEALING RING, M10
VMRS 044-003-031-18-03-00-00

JOB#2 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2024EP60T**

CONDITION CHECK AND ADVISE AIR COMPRESSOR LEAKING

CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: CHECK AND ADVISE AIR COMPRESSOR LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: O-RING - AIR COMPRESSOR / 013-009-027

CAUSE: LEAKING

PFP: DDE A0021311280

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- air compressor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

107-6929F SEALS, AIR COMPRESSOR, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0309976645	OIL SUPPLY O-RING, AIR COMPRES	
1	203F/DDE A0239977145	O-RING, TOROIDAL SEALING, GEN	
1	203F/23-14393-000	UNION-PTC,.25 NT TO .25 NT	
1	203F/F4HZ 3K506 C	MOUNTING GASKET-POWER STEERING	
1	203D/OWI 23519396	COOLANT DDC PWRCOL ELC OAT 50/	
1	203F/DDE A4722005052	LINE, COOLANT SUPPLY, ONE CYL	
1	203F/DDE A4722004251	A/C COOLANT RETURN LINE	
	VMRS	013-009-027-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#3 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2024EP61T

CONDITION CHECK AND ADVISE OIL COOLER MOD LEAKING
CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: CHECK AND ADVISE OIL COOLER MOD LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - OIL AND COOLANT MODULE / 045-012-062
CAUSE: LEAKING
PFP: DDE A4721841980
CORRECTION: REPLACE
WARRANTY STATUS: DTNA COVERAGE AVAILABLE
PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:
- oil mod is leaking SH
101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:
104-6201A MOUNTING SEALS OR GASKET, OIL COOLANT MODULE, R/R WITH STEAM CLEAN AND REPAIR
VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4721841980	SEAL	
1	203F/DDE A4722030080	SEAL, COOLANT THERMOSTAT	
	VMRS	045-012-062-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#4 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2024EP62T**

CONDITION CHECK AND ADVISE PASS THROUGH SEALS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE PASS THROUGH SEALS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SEAL - ADAPTER, FUEL INJECTOR LINES / 044-003-147

CAUSE: LEAKING

PFP: DDE A4720780180

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- pass through seals are leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

102-6222A LINE OR LINE SEAL, HIGH PRESSURE FUEL INJECTOR, ONE, R/R WITH STEAM CLEAN AND

REPAIR VALIDATION SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

102-7100C LINE OR LINE SEAL, FUEL INJECTOR, EACH ADDITIONAL SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
6	203F/DDE A4720780480	SEAL, FUEL INJECTOR LINE, PASS	
1	203X/SIL 5089	BRAKLEEN	
	VMRS	044-003-147-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#5 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2024EP63T**

CONDITION CHECK AND ADVISE INJECTRO HARNESS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE INJECTRO HARNESS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: WIRING HARNESS - ELECTRONIC INJECTORS / 044-014-002

CAUSE: LEAKING

PFP: DDE A4721506333

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- front and rear injector harness leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

286-6105E HARNESS, FUEL INJECTOR WIRING, ONE OR BOTH, R/R WITH STEAM CLEAN SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4720160121	SEAL, ROCKER COVER	
1	203F/DDE A4721506233	WIRING HARNESS, FUEL INJECTOR,	
1	203F/DDE A4721506333	WIRING HARNESS, FUEL INJECTOR,	
	VMRS	044-014-002-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#6 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2024EP64T**

CONDITION CHECK AND ADVISE CAM SENSOR LEAKING

CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: CHECK AND ADVISE CAM SENSOR LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SENSOR - CAMSHAFT POSITION / 045-021-037

CAUSE: LEAKING

PFP: DDE A0071535928

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- cam sensor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

283-6180A SENSOR, CAMSHAFT POSITION, R/R SH

101-6941E DETROIT REPAIR VALIDATION SH

939-6041A STEAM CLEAN, SPOT OF FAILURE SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0071535928	SENSOR, CAMSHAFT POSITION	
	VMRS	045-021-037-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#7 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2024EP65T

CONDITION CHECK AND ADVISE OIL PRESSURE SENSOR LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE OIL PRESSURE SENSOR LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: SENSOR - ENGINE OIL PRESSURE / 045-021-029

CAUSE: LEAKING

PFP: DDE A0071530828

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: RETURN (RETURN ALL PARTS)

NOTES/DIAGNOSTIC TIMES:

- oil psi sensor leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

283-6190E SENSOR, OIL PRESSURE, R/R WITH STEAM CLEAN SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE N000000001070	SEALING RING, M16	
1	203F/DDE A0111539228	SENSOR, OIL PRESSURE	
	VMRS	045-021-029-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#8 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2024EP66T

CONDITION CHECK AND ADVISE FRONT COVER LEAKING

CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: CHECK AND ADVISE FRONT COVER LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - FRONT COVER, LOWER / 045-001-020

CAUSE: LEAKING

PFP: DDE A4720110180

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- front cover leaking SH
101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6322E FRONT ENGINE COVER, LOWER, R/R WITH STEAM CLEAN AND REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4700111007	CRANKCASE COVER FRT	
1	203F/DDE A4720110380	MOUNTING GASKET, FRONT ENGINE	
1	203F/DDE A0169970646	OIL SEAL, CRANKSHAFT, FRONT	
1	203D/LOC 37464	RTV 5699™ Grey High Performanc	
1	203F/DDE A4730140122	SEAL, OIL PAN MOUNTING	
	VMRS	045-001-020-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#9 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2024EP67T

CONDITION CHECK AND ADVISE TURBO DRAIN PIPE LEAKING
CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: CHECK AND ADVISE TURBO DRAIN PIPE LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: O-RING - OIL DRAIN TUBE, TURBOCHARGER / 043-004-173
CAUSE: LEAKING
PFP: DDE A0189973145
CORRECTION: REPLACE
WARRANTY STATUS: DTNA COVERAGE AVAILABLE
PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:
- turbo drain pipe leaking at block SH
101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:
11A-6506E OIL RETURN LINE AND FITTINGS, TURBOCHARGER, R/R, WITH STEAM CLEAN AND REPAIR
VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A5411870080	GASKET TURBOCHARGER OIL RETURN	
1	203F/DDE A0189973145	O-RING - GENERAL PURPOSE	
	VMRS	043-004-173-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#10 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2024EP68T

CONDITION CHECK AND ADVISE OIL SEP LEAKING

CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: CHECK AND ADVISE OIL SEP LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: GASKET - BREATHER ASSEMBLY, CRANKCASE VENTILATION /
045-014-008

CAUSE: LEAKING

PFP: DDE A4720180780

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- breather leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6851E CRANKCASE BREATHER ASSEMBLY, R/R WITH STEAM CLEAN SH

101-6941E DETROIT REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A4720180780	GASKET, CRANKCASE BREATHER	
1	203X/SIL 5089	BRAKLEEN	
	VMRS	045-014-008-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#11 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# **BWFD2024EP69T**

CONDITION CHECK AND ADVISE BLOCK FITTING LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE BLOCK FITTING LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: FITTING - BREATHER / 045-014-017

CAUSE: LEAKING

PFP: DDE A0049971371

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- breather fitting leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6855E FITTING, CRANKCASE BREATHER PIPE, R/R WITH STEAM CLEAN AND REPAIR VALIDATION

SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0079979271	SCREW-IN FITTING	
	VMRS	045-014-017-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#12 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2024EP70T

CONDITION CHECK AND ADVISE IDLER GEAR COVER LEAKING

CAUSE LEAKING

CORRECTION Techlane :
ORIGINAL COMPLAINT: CHECK AND ADVISE IDLER GEAR COVER LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

NO PRIMARY FAILED COMPONENT

NOTES/DIAGNOSTIC TIMES:
- idler gear cover on the back of the head to be leaking SH

NOTES/REPAIR TIMES:
- REMOVED THE AIR FILTER HOUSING, PIPING, AND THE BRACKETS. UNBOLTED THE COVER AND REMOVED IT. CLEANED OFF THE HEAD AND COVER. R/R THE O RING. INSTALLED THE COVER AND TORQUED IT TO SPEC. INSTALLED THE BRACKETS, PIPING, AND THE AIR FILTER HOUSING. STARTED THE TRUCK UP AND LET IT REACH OPERATIGN TEMP. CHECKED THE TRUCK FOR ANY LEAKS. FOUND NO LEAKS AT THIS TIME. JOB COMPLETE.
SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
1	203F/DDE A0309979045	O-RING, CYLINDER HEAD CLOSING	
	VMRS	045-007-055-18-03-00-00	

INVOICE NO.	R203179101:01
INVOICE DATE	11/14/2024
P.O. NUMBER	
VIN	3AKJHHDR8MSMZ5506
UNIT	724

CUST#	&SWD	ADVISOR	6675	ENGINE		COLOR	GRN	SCHED	11/8/24	UNTID	716963
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

JOB#13 TCIUS SWD COURTESY INSPECTION ADDED ITEM

CLAIM NUMBER# BWFD2024EP71T

CONDITION CHECK AND ADVISE FRONT CAM CAPS LEAKING

CAUSE LEAKING

CORRECTION Techlane :

ORIGINAL COMPLAINT: CHECK AND ADVISE FRONT CAM CAPS LEAKING

MODIFIED COMPLAINT: N/A

FAULT CODES: N/A

PRIMARY FAILED COMPONENT: PLUG - OIL GALLEY, CAMSHAFT / 045-008-004

POSITION: Front

CAUSE: LEAKING

PFP: DDE A4729980290

CORRECTION: REPLACE

WARRANTY STATUS: DTNA COVERAGE AVAILABLE

PARTS DISPOSITION: SCRAP

NOTES/DIAGNOSTIC TIMES:

- front cam caps leaking SH

101-010AE DETROIT ENGINE EXTERNAL OIL LEAK DIAGNOSTICS - EASY SH

NOTES/REPAIR TIMES:

101-6712A PLUG, CAMSHAFT HOUSING, FRONT, R/R, WITH STEAM CLEAN AND REPAIR VALIDATION SH

TECHLIT PROCEDURES: N/A

QTY	ITEM	DESCRIPTION	TECHNICIAN
	00	GENERAL REPAIR	TECH NO. 2258
2	203F/DDE A4729980290	PLUG, CAMSHAFT HOUSING, 40 MM	
2	203F/DDE A4722000154	COUPLING - WATER MANIFOLD	
	VMRS	045-008-004-18-03-01-00	

CUST#	&SWD	ADVISOR	6675	ENGINE	COLOR	GRN	SCHED	11/8/24	UNTID	716963	
YEAR	21	MAKE	FTL	MODEL	PT126	MILES	445068	INSVC	12/31/99	ACCT	CHG

SIGNATURE X