

Priced Work Order

Work Order #465 001599

272 HERRING ROAD

Page

PRICED WORK ORDER

For Purchase Order APPROVAL ONLY For Questions or Concerns:

MORE: BAYS, EXPERTISE, SOLUTIONS. THANK YOU AND STAY SAFE!

Service Dept Manager:

FAIR PLAY, SC 29643- (864) 280-7320

JOSHUA HONEA 864-280-7320

1599 License P 465 Company Name Driver's Name DRIVER CELL# 2259397120 ROYAL3 INC TITUS TRIP# Authorized by Address VIS Pymt. PO# Card # 6850 W 63RD STREET Work Performed by Tax Exempt # Written by Paid Completed Written Begun CHICAGO IL 60638 12/13/24 13:47 Engine Make/Model Tractor # Make/Model VIN # Year icense # Odometer DD15 20 MLMP3401 FTL 674885 CASCADIA P1070316 IL Trailer # Make/Model Hubodometer Year icense #

TN

U769074

Work Requested

289474

719

TITUS REQUESTS:

GREAT DANE

C/A AIR LEAK WHEN BRAKES ARE ENGAGED

UNIT SVCD: TRCTR & TRLR CB: 6305661266 ERIC

0.0

SERVICE	PLU#	PART NUMBER	DESCRIPTION	UOM	REG. PRICE	PRICE	QTY	EXTENDED AMOUNT
LET	996 001	SAP # 0001605124	PARTS RUN	EA	150.00	150.00	1.00	150.00
SL	551 999	HVD9978, SAP #0001603702	AIR BAG	EA	132.21	132.21	1.00	132.21
SL	504 007	330-3107, SAP #0001603789	330 3107 AXLE GASKET	EA	7.13	7.13	1.00	7.13
TRHB			HUB CAP OR AXLE GASKET REPI	ACE			1.00	44.99
TRHB		LABOR TO REPLACE HUB CAP OR ATLE GASKET						
TRHB	998 002	777777, SAP #0001606876	STANDARD SERVICE LABOR	HR			. 60	
SL	997 002	SAP # 0001605126	SHOP SUPPLY/ENVIRONMENTAL E	EE EA	29.58	29.58	1.00	29.58
SL	998 004	LABOR, SAP #0001606877	MECHANICAL HOURLY LABOR	HR	126.99	126.99	1.25	158.74
		Specifically listed in this variety request; however, Customer de order. Customer hereby release and/or issues on Customer's variety including, but not limited to component parts or other item	clines any additional service ses TA from any claims or lia chicle/trailer which is not s any inspection, evaluation	nds TA offers not specifically or recommen	rs additional fically listed ted to service listed in the dation relate	services up ed on this wo ee work, cond ne work order	on rk itions	
Parts Labor	202 2		0.00	n-taxable :	353.73 168.92	ENV/WS TOTAL	T Tax:	0.00

Technician Comments

TRUCK WAS ALREADY IN BAY AND TAGGED OUT. TOOK OVE R PASSENGER SIDE FORNT AIR BAG FROM PREVIOUS TECH. GS AND IN THE PROCESS OF REMOVING TIRES FROM TRIAL SUPERVISED APPRENTICE ON PROPER REMOVAL OF AIRBA ER FOUND THAT RIGHT FRONT WHEEL STUD LUGNUT KEPT S PINNING AND WOULD NOT LOOSEN OR TIGHTEN INDICATING THAT IT IS STRIPPED OF ITS THREADS. ADVISED COMP ANY OF ISSUE AND COMPANY DID NOT WANT US TO PROCEE

Remarks

* * * DO NOT PAY * * *

* * * * PRICED WORK ORDER - FOR PURCHASE ORDER ISSUANCE ONLY * * * *

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged. on above vehicle to secure the amount of repairs therein.

In the event that you, the customer, authorize commencement but do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work. Such charges will be directly related to the actual amount of labor or parts involved in the inspection, repair or service.

Credit Card Authorization Consent Form

hereby authorize TA Truck Service
ny credit card for services rendered.
\$532.79 \$(US Dollars)
or Cardholder
arges described on this form, assume full agree to honor and abide by the terms of payment. I ervice #0465 Fairplay, SC Terms and Conditions.
Date:

A STATE OF THE STA

ADDITIONAL REMARKS

TECHNICIAN COMMENTS CONTINUED:

D ANY FURTHER AND THAT THEY WOULD FIND ANOTHER PLA CE TO DO THE WORK. SUPERVISED AND HELPED APPRENTICE PUT AIRBAG BACK TO ORIGINAL AND ALSO HAD LEAKIN G AXLE GASKET ON REAR AXLE PASSENGER SIDE. SUPERVISED AND HELPED APPRENTICE THROUGH CHANGING AXLE GASKET. JAR-JAR-JAR-JR-JR-JR TORQUED ALL LUGNUTS POSSIBLE TO 475 FOOT POUNDS. AXLE GASKET WAS ON TRACTOR.