

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RIVERS	SHONTERRO	104179501	SC										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		4	Vehicle Inspections:		1	Hazmat Inspections		0					
Driver Out-of-service Inspections:		0	Vehicle Out-of-service Inspections:		1	Hazmat Out-of-service Inspections:		0					
Driver Out-of-service Rate:		0%	Vehicle Out-of-service Rate:		100%	Hazmat Out-of-service Rate:		0%					
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	01/25/2022	2535460	KANG TRANSPORT CO LLC	RIVERS, SHONTERRO	104179501	SC	01/05/2000	OH	1532001851	N	3	1	
Driver Violation:		392.2	State/Local Laws - Speeding 15 or more miles per hour over the speed limit				NON-OOS						

Report executed at: 12/2/2024 8:08:04 AM

MCMIS snapshot date: 10/25/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	05/20/2022	80806	J B HUNT TRANSPORT INC	RIVERS, SHONTERRO	104179501	SC	01/05/2000	SC	H302002480	N	2	5
Vehicle Violation:		393.78	Wipers - Inoperative / missing / damaged wipers			NON-OOS						
Vehicle Violation:		393.75(a)(1)	Tire-ply or belt material exposed			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			OOS						
3	09/12/2024	1994664	TRYTIME TRANSPORT LLC	RIVERS, SHONTERRO	104179501	SC	01/05/2000	WV	PSC1670494	N	3	0
4	09/19/2024	1994664	TRYTIME TRANSPORT LLC	RIVERS, SHONTERRO	104179501	SC	01/05/2000	FL	3861000604	N	3	0

Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.78	Wipers - Inoperative / missing / damaged wipers								1	0		
393.75(a)(1)	Tire-ply or belt material exposed								1	0		
393.9(a)	Inoperable Required Lamp								3	2		
392.2	State/Local Laws - Speeding 15 or more miles per hour over the speed limit								1	0		

The summary counts and rates only include violations that were attributable to RIVERS, SHONTERRO.

Report executed at: 12/2/2024 8:08:04 AM

MCMIS snapshot date: 10/25/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>