

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
LEFRID		LEFRID		583AT6181			IA								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		5		Vehicle Inspections:		3		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	06/21/2022	1870373	GTS TRANSPORTATION CORPORATION	LEFRID, YOUNESS	583AT6181	IA	12/25/1986	UT	22TF000237	N	1	1			
Vehicle Violation:		393.55(e)		No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998				NON-OOS							

Report executed at: 11/29/2024 11:40:35 AM

MCMIS snapshot date: 10/25/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	10/03/2023	2513961	HERMES NVC CORP	YOUNESS, LEFRID	583AT6181	IA	12/25/1986	NE	T180000016	N	3	0
3	04/08/2024	2513961	HERMES NVC CORP	LEFRID, YOUNESS	583AT6181	IA	12/25/1986	SD	5790000225	N	1	0
4	04/28/2024	2513961	HERMES NVC CORP	LEFRID, YOUNESS	583AT6181	IA	12/25/1986	IL	4069330269	N	3	0
5	09/01/2024	2513961	HERMES NVC CORP	LEFRID, YOUNESS	583AT6181	IA	12/25/1986	WA	2059000809	N	1	0
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.55(e)		No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998							1		0	

The summary counts and rates only include violations that were attributable to LEFRID, LEFRID.

Report executed at: 11/29/2024 11:40:35 AM

MCMIS snapshot date: 10/25/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.